



Polymath garage

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 201605123Z

Cecilia.

ESTIMATED REPAIR CHECKLIST

TO : AXA INSURANCE	VEHICLE REGISTRATION NO.: SLF1244H
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL: HONDA / ACCORD
CLAIM TYPE : 3RD PARTY CLAIM	CHASSIS NUMBER: MRHCR1630GP000058
ACCIDENT DATE/TIME :	CONTACT PERSON : SEBASTIAN (97527592)

PARTS	QTY	PER UNIT	PRICES
1 REAR BUMPER <i>Distorted</i>	1	\$ 680.50	\$ 680.50 ✓
2 REAR BUMPER SIDE HOLDER LH <i>Damaged</i>	1	\$ 29.10	\$ 29.10 ✓
3 REAR BUMPER MUDFLAP LH <i>Ryie</i>	1	\$ 61.80	\$ 61.80 x.
4 TAILLAMP LH <i>crushed</i>	1	\$ 591.40	\$ 591.40 ✓
5 REAR LH FENDER <i>Distorted</i>	1	\$ 1,119.00	\$ 1,119.00 ✓
6 REAR LH FENDER AIR VENT <i>NE NEU</i>	1	\$ 62.40	\$ 62.40 x.
7 REAR LH FENDER INNER SHIELD <i>deformed</i>	1	\$ 132.80	\$ 132.80 ✓
8 REAR LH KNUCKLE ARM	1	\$ 388.90	\$ 388.90 x
9 REAR LH WHEEL HUB C/W BEARING	1	\$ 215.60	\$ 215.60 x
10 REAR LH SHOCK ABSORBER	1	\$ 374.50	\$ 374.50 x
11 REAR LH LATERAL LINK	1	\$ 185.40	\$ 185.40 x
12 REAR LH STAY ARM	1	\$ 198.50	\$ 198.50 x
13 REAR WINDSCREEN MOULDING <i>NEU</i>	1	\$ 151.80	\$ 151.80 ✓
		SUBTOTAL :	\$ 4,191.70
		LESS 20% :	\$ 838.34
		PARTS TOTAL :	\$ 3,353.36

2704.60
less 20%: 2163.68

SPECIAL NETT	QTY	PER UNIT	PRICES
1 Rear BUMPER CLIPS <i>NEU</i>	1 SET	\$ 30.00	\$ 30.00 ✓
2 REVERSE SENSOR <i>NEU NEU</i>	1 SET	\$ 280.00	\$ 280.00 x.
3 REAR FENDER INNER SHIELD CLIPS <i>NEU</i>	1 SET	\$ 30.00	\$ 30.00 ✓
4 REAR LH WHEEL RIM <i>At</i>	1	\$ 800.00	\$ 800.00 450
5 REAR LH TYRE <i>NEU NEU</i>	1	\$ 280.00	\$ 280.00 x
6 REAR WINDSCREEN SEALANT <i>NEU</i>	1 SET	\$ 60.00	\$ 60.00 ✓
		S/N TOTAL :	\$ 1,480.00

570

LABOUR CHARGES	PRICES	ADJUSTMENT
1 PANEL BEATING	\$ 1,000.00	600
2 SPRAY PAINTING	\$ 1,000.00	500
3 WIRING	\$ 100.00	30
4 TO REMOVE REVERSE SENSOR	\$ 100.00	50
5 TO REMOVE UPHOLSTERY	\$ 150.00	60
6 TO SPRAY TUFF COAT	\$ 150.00	60
7 TO REMOVE REAR WINDSCREEN	\$ 180.00	120
8 TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80
9 TO REMOVE REAR UNDERCARRIAGE	\$ 300.00	x
LABOR TOTAL :		\$ 3,130.00

1500



Polymath garage

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 201605123Z

ESTIMATE REPORT	
TOTAL PARTS COST:	\$ 4,833.36
TOTAL LABOUR COST:	\$ 3,130.00
TOTAL REPAIR COST:	\$ 7,963.36
PART BY PART / LUMP SUM:	
NO. OF REPAIR DAYS:	

SURVEYOR DETAILS	
SURVEYOR NAME:	Adrian Lj
CONTACT:	
EMAIL:	
DATE :	
TIME :	

total: 4233.68

2/s: 3350.

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____