

No.	Special Nett Items			Amount
1	Front bumper clips	1set		\$ 301.00 70.00
2	Front grille clips	1set		\$ 50.00
3	Front number plate	1		\$ 70.00
4	Bonnet inner heat insulator clips	1set		\$ 70.00
5	Radiator coolant	1		\$ 301.00 60.00

				60.00

	Labour and painting		Amount
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas		\$ 800.00 1,000.00 ✓
2	Spray painting on affected areas and panels		\$ 800.00 1,000.00 ✓
3	Check wiring and lighting system		\$ 50.00 } NNX
4	Apply rust coating chemical on affected areas and panels		\$ 30.00 }
5	Remove and replace aircon condenser, pipes and sensor to assist repair		\$ 80.00 200.00 ✓
6	Remove and replace radiator assy, hoses and fan assy to assist repair		\$ 80.00 200.00 ✓
7	Refocus and adjust headlamps assy		\$ 80.00 NNX

Total: \$ ~~1760.00~~ 8,770.97

Survey & Resurvey

1545 hrs
Retiree Mm
10/2/2022

Lump sum repair
Repair days 6

Parts 3370.85

SN 60.00

Labour 1760.00

5190.85

@20% 1038.17

4152.68

LS 4/50/2

TGum Mm
17/2/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: