

OPTIMA WERKZ™ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W

www.ow.sg

f /OptimaWerkz

● /OptimaWerkz

Date: 24/01/2022

Vehicle No: SLN5407L

Model: TOYOTA AQUA HYBRID 1.5S CVT

Chassis: NHP106587753-2017

Reg. Year: 2017

Third Party Insurer: CHINA TAIPING

Third Party Veh No: YP8173B

Date of Accident: 24/01/2022

Estimator: TING AN

Surveyor:

Not Notified

1/1/2022 @ 3300h

Resurvey After Repair

4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR RH	1		<i>R</i> \$1,241.00
2	FRONT DOOR INNER TRIM BOARD RH	1		<i>Ln</i> \$914.00
3	FRONT DOOR FRAME PROTECTIVE STICKER RH	1		<i>Ln</i> \$50.00
4	FRONT DOOR OUTER HANDLE RH	1		<i>Ln</i> \$375.00
5	FRONT DOOR INNER LOCK RH	1		<i>R</i> \$560.00
6	FRONT DOOR GLASS LOWER OUTER MOULDING RH	1		<i>Dis R</i> \$65.00
7	REAR DOOR RH	1		<i>R</i> \$1,045.00
8	REAR DOOR INNER TRIM BOARD RH	1		<i>Bu</i> \$763.00
9	REAR DOOR OUTER HANDLE RH	1		<i>Ln</i> \$375.00
10	REAR DOOR LOCK RH	1		<i>R</i> \$560.00
11	REAR DOOR FRAME PROTECTIVE STICKER RH	1		<i>Ln</i> \$50.00
12	REAR DOOR GLASS RH	1		<i>Shatter</i> \$863.00
13	REAR DOOR GLASS LOWER OUTER MOULDING RH	1		<i>R</i> \$65.00
14	REAR DOOR REGULATOR RH	1		<i>R</i> \$201.00
15	REAR DOOR WINDOW MOTOR RH	1		<i>Ln</i> \$847.00
16	REAR DOOR UPPER HINGE RH	1		<i>R</i> \$90.00
17	REAR DOOR LOWER HINGE RH	1		<i>R</i> \$90.00
18	REAR DOOR CHECKER RH	1		<i>Ln</i> \$195.00
19	REAR DOOR SPEAKER RH	1		<i>R</i> \$454.00
SUB TOTAL				\$8,803.00
LESS 25%				-\$2,200.75
PARTS TOTAL				\$6,602.25

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR INNER TRIM BOARD CLIPS RH	1		<i>Ln</i> \$60.00
2	REAR DOOR INNER TRIM BOARD CLIPS RH	1		<i>Ln</i> \$60.00
S/N TOTAL				\$120.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD

Co. Reg. No. 201212455W

www.ow.sg

f /OptimaWerkz

● /OptimaWerkz

Date: 24/01/2022
Vehicle No: SLN5407L
Model: TOYOTA AQUA HYBRID 1.5S CVT
Chassis: NHP106587753-2017
Reg. Year: 2017

Third Party Insurer: CHINA TAIPING
Third Party Veh No: YP8173B
Date of Accident: 24/01/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

3000
\$600.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR RH, REAR DOOR RH & ETC.

4500
\$600.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

2000
\$120.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

600
\$120.00

TO TUFF KOTE & UNDERSEAL MATERIALS & ETC.

300
\$120.00

TO CHECK WRING & CENTRAL LOCKING SYSTEM.

200
\$150.00

LABOUR TOTAL \$1,710.00

TING AN

TOTAL \$8,432.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

