51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd DATE: 26/1/2022

Survey details

Date of loss	19/1/2022
Date of appointment	25/1/2022
Date of survey	25/1/2022
Location of survey	464 Macpherson Road Singapore 368182
	Repairer: MOTO 51 PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	FBP 6120P
Make and Model	YAMAHA YS-125
Date of registration	10/5/2019
Excess	
Market Value	\$11,000.00
Parf Rebate	\$2,442.00
Nett Loss	\$8,558.00

Repair details

Initial Estimate	

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	
Normalian of days of manain	2 dans (and)

Number of days of repair 3 days (est)

Remarks:

Daamges Consistent

The estimated repair cost of the damaged vehicle is

in the region of \$2,000.00-\$3,000.00