

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

YES CAR LEASING PTE LTD
210 TURF CLUB ROAD #LOT-B21 THE
GRANDSTAND
SINGAPORE 287995

Contact : 64635155 97297769

TAX INVOICE

Repair Code : CLM13698

Date in : 07/05/2017

Vehicle Num. : SGX7161M

Model : TOYOTA ESTIMA 2.4 A

Chassis/Eng# : ACR500043448/2AZF057046

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount	
FRONT BUMPER <i>Repis</i>	1	1712.40	1,712.40	+
FRONT BUMPER SIDE RETAINER L/R <i>xe n</i>	2	113.45	226.90	+
FRONT LH ABS SENSOR <i>xe n</i>	1	397.10	397.10	+
FRONT LH DOOR <i>Dented</i>	1	1004.00	1,004.00	✓
FRONT LH DOOR MECHANISM LOCK <i>xe n</i>	1	509.00	509.00	+
FRONT LH DOOR TRIM BOARD <i>xe n</i>	1	780.00	780.00	+
FRONT LH DOOR WEATHER STRIP <i>xe n</i>	1	215.00	215.00	+
FRONT LH FENDER <i>Dented</i>	1	700.00	700.00	✓
FRONT LH FENDER INNER SHIELD <i>xe n</i>	1	372.25	372.25	+
FRONT LH HEADLAMP <i>NE NEW</i>	1	1912.40	1,912.40	+
FRONT LH KNUCKLE ARM <i>Dmgd</i>	1	581.60	581.60	✓
FRONT LH KNUCKLE ARM BEARING <i>Dmgd</i>	1	161.40	161.40	✓
FRONT LH LOWER ARM <i>Best</i>	1	374.40	374.40	✓
FRONT LH LOWER ARM BALL JOINT <i>Best</i>	1	166.78	166.78	✓
FRONT LH SHOCK ABSORBER <i>Best</i>	1	372.55	372.55	✓
FRONT LH SHOCK ABSORBER TOP MOUNTING <i>xe n</i>	1	261.60	261.60	+
FRONT LH STABILIZER LINKAGE <i>xe n</i>	1	195.40	195.40	+
FRONT LH WHEEL HUB BEARING <i>xe n</i>	1	152.70	152.70	+

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

YES CAR LEASING PTE LTD
 210 TURF CLUB ROAD #LOT-B21 THE
 GRANDSTAND
 SINGAPORE 287995

Contact : 64635155 97297769

TAX INVOICE

Repair Code : CLM13698

Date in : 07/05/2017

Vehicle Num. : SGX7161M

Model : TOYOTA ESTIMA 2.4 A

Chassis/Eng# : ACR500043448/2AZF057046

REAR AXLE ASSY	1	3027.70	3,027.70	+
REAR BUMPER	1	1125.70	1,125.70	+
REAR BUMPER SIDE RETAINER L/R	2	61.70	123.40	+
REAR LH FENDER	1	971.20	971.20	+
REAR LH FENDER INNER SHIELD	1	231.70	231.70	+
REAR LH SHOCK ABSORBER	1	182.55	182.55	+
REAR LH WHEEL HUB BEARING	1	581.40	581.40	✓
SLIDING LH DOOR	1	1217.25	1,217.25	+

Subtotal before discount

17,556.38

Percentage discount 25%

4,389.10

Sub-total 1

13,167.29

FRONT BUMPER CLIPS - SET	1	50.00	50.00	+
FRONT LH DOOR TRIM BOARD CLIPS - SET	1	60.00	60.00	+
FRONT LH FENDER INNER SHIELD CLIPS - SET	1	50.00	50.00	+
FRONT LH SPORT RIM	1	600.00	600.00	+
FRONT LH TYRE	1	480.00	480.00	+
REAR BUMPER CLIPS - SET	1	30.00	30.00	+
REAR LH FENDER INNER SHIELD CLIPS - SET	1	30.00	30.00	+

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

YES CAR LEASING PTE LTD
210 TURF CLUB ROAD #LOT-B21 THE
GRANDS AND
SINGAPORE 287995

Contact : 64635155 97297769

TAX INVOICE

Repair Code : CLM13698

Date in : 07/05/2017

Vehicle Num. : SGX7161M

Model : TOYOTA ESTIMA 2.4 A

Chassis/Eng# : ACR500043448/2AZF057046

REAR LH SPORT RIM	1	600.00	600.00	500
REAR LH TYRE	1	480.00	480.00	X
Subtotal before discount			2,380.00	
Percentage discount 0%			0.00	
Sub-total 2			2,380.00	
Parts-total			15,547.29	

LABOUR.

- To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.
- To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.
- To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.
- To road test driving, check and resetting wheel alignments system.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

200.00 80
300.00 220
450.00 100
180.00 80
100.00 X
100.00 80
1,600.00 100
1,500.00 700
120.00 50

4,550.00

20,097.29

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6266.59
L/S: SK
65 days.

SK