



CL A

5/15/20

|            |   |                    |
|------------|---|--------------------|
| ESTIMATE   | : | ACCIDENT REPAIRS   |
| WORKSHOP   | : | UBI ROAD 1         |
| CONTACT NO | : | 6366 2323          |
| FAX NO     | : | 6841 1183          |
| REFERENCE  | : | PA/OD/0054/2022/JT |
| DATE       | : | 21-Jan-22          |
| WIP        | : | 64439              |

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/1/22

**Tel: 6880 4602 - Fax: 6880 4838**

|                   |   |                                              |
|-------------------|---|----------------------------------------------|
| OWNER'S NAME      | : | MS SHARON TAN HWEI CHING (CHEN HUIZHEN)      |
| ADDRESS           | : | 21 NEWTON ROAD<br>#04-20<br>SINGAPORE 307954 |
| TELEPHONE         | : | HP +65 90677590                              |
| TYPE OF CLAIM     | : | OWN DAMAGE CLAIM                             |
| POLICY NO         | : | 2070054657-01                                |
| VEHICLE NO        | : | <b>SLD 7888 X</b>                            |
| MODEL CODE        | : | AUDI A3 SB 1.0 TFSI S                        |
| MODEL YEAR        | : | 23/3/2020                                    |
| ENGINE NO         | : | CHZ C38056                                   |
| CHASSIS NO        | : | WAUZZZ8VXLA035349                            |
| MILEAGE           | : | -                                            |
| DATE IN           | : | -                                            |
| ESTIMATED BY      | : | JOHNNY BOO / ALLAN WU                        |
| ACCIDENT DATE     | : | 21-Jan-22                                    |
| PLACE OF ACCIDENT | : | PIE EXIT 16A                                 |

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLD 7888 X

| S/N                         | NATURE OF JOBS                                                                                                                                                                                              | ESTIMATED CHARGES     | SURVEYOR'S RECOMMENDATIONS                                                    |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|-------------------------------------------------------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.                                                                               | S/N \$ 360.00         | x                                                                             |
| 2                           | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                                                                      | S/N \$ 700.00         | ?                                                                             |
| 3                           | TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACUUM AND REGAS                                                   | S/N \$ 1,400.00       | ?                                                                             |
| 4                           | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL PARTS REMOVED. | \$ 4,900.00           | 1000 (Without <sup>lock</sup> carrier)<br>2250 (With <sup>lock</sup> carrier) |
| 5                           | TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDER AND BOTH UPPER A-PILLAR.                                                                                                                         | \$ 5,000.00           | 1100                                                                          |
| 6                           | TO REAPPLY PAINT COATING FOR FRONT BONNET AND FRONT BUMPER. (BY OWNER)                                                                                                                                      | \$ 400.00             | 350                                                                           |
| 7                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                                              | S/N \$ 192.00         | ✓                                                                             |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                             | <b>: \$ 12,952.00</b> |                                                                               |

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 7888 X

ESTIMATED LABOUR CHARGES FOR ACCIDENT

PARTS & PRICES

DAMAGED PARTS & PRICES

| REMARKS                      | S/N | PARTS DESCRIPTION                                      | QTY | S/NETT              | REMARKS |
|------------------------------|-----|--------------------------------------------------------|-----|---------------------|---------|
|                              | 1   | FRONT BUMPER <i>Replaced</i>                           | 1   | \$ 2,146.00         | ✓       |
|                              | 2   | FRONT BUMPER FIXING PARTS <i>new</i>                   | 1   | \$ 195.00           | +       |
|                              | 3   | FRONT BUMPER GUIDE SECTION - LH / RH ?                 | 2   | \$ 86.00            | ?       |
|                              | 4   | FRONT BUMPER GRILLE - CENTER <i>new</i>                | 1   | \$ 179.00           | +       |
|                              | 5   | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i> | 1   | \$ 332.00           | +       |
|                              | 6   | FRONT BUMPER CLOSING ELEMENT - LH / RH ?               | 2   | \$ 636.00           | ?       |
|                              | 7   | RADIATOR GRILLE <i>Cracked</i>                         | 1   | \$ 1,406.00         | ✓       |
|                              | 8   | RADIATOR CLOSING ELEMENT ?                             | 1   | \$ 210.00           | ?       |
|                              | 9   | AIR COND STICKER ?                                     | 1   | \$ 9.00             | -       |
|                              | 10  | CAUTION STICKER <i>3 me</i>                            | 1   | \$ 16.00            | -       |
|                              | 11  | FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>     | 2   | \$ 420.00           | +       |
|                              | 12  | FRONT BUMPER FOAM FILLER PIECE ?                       | 1   | \$ 211.00           | ?       |
|                              | 13  | FRONT BUMPER REINFORCEMENT BEAM ?                      | 1   | \$ 847.00           | ?       |
|                              | 14  | FRONT BUMPER REINFORCEMENT BEAM COVER ?                | 1   | \$ 136.00           | ?       |
|                              | 15  | HORN - LH / RH ?                                       | 2   | \$ 426.00           | ?       |
|                              | 16  | BONNET <i>Buckled</i>                                  | 1   | \$ 3,370.00         | ✓       |
|                              | 17  | BONNET ATTACHMENT PARTS <i>new</i>                     | 1   | \$ 172.00           | +       |
|                              | 18  | BONNET HINGE - LH / RH <i>new</i>                      | 2   | \$ 136.00           | +       |
|                              | 19  | FRONT FENDER UPPER INNER COVER - LH / RH <i>new</i>    | 2   | \$ 92.00            | +       |
|                              | 20  | BONNET EDGE PROTECTION <i>new</i>                      | 1   | \$ 31.00            | ?       |
| <b>SUB TOTAL SPARE PARTS</b> |     |                                                        | :   | <b>\$ 11,056.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



SINGAPORE 55 UBI ROAD 1, SINGAPORE 408699

FAX : 6841 1183 TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

SINGAPORE 55 UBI ROAD 1, SINGAPORE 408699

FAX : 6841 1183 TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5LD 7888 X

## DAMAGED PARTS & PRICES

## DAMAGED PARTS & PRICES

| S/N | PARTS DESCRIPTION                     | QTY | S/NETT       | REMARKS |
|-----|---------------------------------------|-----|--------------|---------|
| 21  | BONNET CATCH HOOK UPPER <i>new</i>    | 1   | \$ 100.00    | X       |
| 22  | BONNET STRIKER - LH / RH <i>new</i>   | 2   | \$ 246.00    | X       |
| 23  | BONNET CATCH HOOK LOWER <i>new</i>    | 1   | \$ 71.00     | ✓       |
| 24  | BONNET MICRO-SWITCH - LH / RH ?       | 2   | \$ 455.00    | ?       |
| 25  | BONNET BOWDEN CABLE - CENTER ?        | 1   | \$ 64.00     | ?       |
| 26  | BONNET RELEASE CABLE COVER ?          | 1   | \$ 11.00     | ?       |
| 27  | BONNET SOUND ABSORBER ?               | 1   | \$ 244.00    | ?       |
| 28  | PLENUM CHAMBER <i>new</i>             | 1   | \$ 199.00    | X       |
| 29  | HEADLIGHT - LH / RH ?                 | 2   | \$ 10,910.00 | ?       |
| 30  | LIFT CYLINDER - LH / RH <i>new</i>    | 2   | \$ 312.00    | ✓       |
| 31  | LIFT CYLINDER HOSE <i>new</i>         | 1   | \$ 78.00     | ✓       |
| 32  | LOCK CARRIER ?                        | 1   | \$ 806.00    | ?       |
| 33  | OUTSIDE TEMPERATURE SENSOR BRACKET ?  | 1   | \$ 21.00     | ?       |
| 34  | A/C CONDENSER <i>new</i>              | 1   | \$ 569.00    | X       |
| 35  | ADDITIONAL RADIATOR <i>new</i>        | 1   | \$ 959.00    | X       |
| 36  | RADIATOR BRACKET - UPPER } <i>new</i> | 2   | \$ 90.00     | X       |
| 37  | RADIATOR BUSH - LOWER }               | 2   | \$ 22.00     | X       |
| 38  | RADIATOR COOLANT ?                    | 6   | \$ 282.00    | ?       |
| 39  | RADIATOR AIR GUIDE - LH / RH ?        | 2   | \$ 56.00     | ?       |
| 40  | RADIATOR SEAL - OUTER RH <i>new</i>   | 1   | \$ 9.00      | X       |

### SUB TOTAL SPARE PARTS

: \$ 15,504.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

# MOORE PREMIUM AUTOMOBILES

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

OR ACCIDENT MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 7888 X HOUR CHARGES FOR ACCIDENT VEHICLE

## PARTS & PRICES

## DAMAGED PARTS & PRICES

| S/N | PARTS DESCRIPTION                             | QTY | S/NETT    | REMARKS |
|-----|-----------------------------------------------|-----|-----------|---------|
| 41  | RADIATOR AIR GUIDE - UPPER CENTER ?           | 1   | \$ 14.00  | ?       |
| 42  | WINDSCREEN WATER DEFLECTOR STRIP - LH / RH AL | 2   | \$ 150.00 | +       |
| 43  | FRONT NO PLATE AL                             | S/N | \$ 100.00 | ✓       |
| 44  | SUNDRIES ?                                    |     | \$ 300.00 | ?       |

TOTAL SPARE PARTS : \$ 27,124.00

TOTAL LABOUR CHARGES : \$ 12,952.00

GRAND TOTAL : \$ 40,076.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*  
 SURVEYED DATE : *25/01/22*  
 AUTHORISED DATE :  
 EXCESS COST :  
 LIABILITY :  
 REMARKS : *Not Authorised, 04 Days (Without load carrier)  
 07 Days (With load carrier)*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
 BODY REPAIR MANAGER

ALLAN WU  
 CLAIMS CONSULTANT