

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLD 7888 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. S/N S	360.00	X
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. <i>W/S & P/S</i> S/N S	700.00	500 S/S
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACUUM AND REGAS S/N S	1,400.00	✓ S/S
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL PARTS REMOVED. S	4,900.00	100 (Without Fender) 2250 (With Lock carrier) S/S
5	TO RESPRAY FRONT BUMPER, BONNET, <u>HINGES</u> , BOTH FRONT FENDER AND BOTH UPPER A-PILLAR. S	5,000.00	1100 + 160 (Hinges) S/S
6	TO REAPPLY PAINT COATING FOR FRONT BONNET AND FRONT BUMPER. (BY OWNER) S	400.00	350
7	TO CARRY OUT DIAGNOSTIC CHECK. S/N S	192.00	✓
TOTAL LABOUR CHARGES		: \$	12,952.00

Car in

16/2/22

wip: 64439.

Kiam/Chay

AIG- Adrian

- 4/7 days.

55, SUB ROAD 1, SINGAPORE 408599

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 7888 X

SPARE PARTS & PRICES

DAMAGED PARTS & PRICES

QTY	S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1		FRONT BUMPER <i>new</i>	1	S	2,146.00 ✓
2		FRONT BUMPER FIXING PARTS <i>new</i>	1	S	195.00 ✓
3		FRONT BUMPER GUIDE SECTION (LH/RH) <i>2H could</i>	2	S	86.00 ✓ 43. sls.
4		FRONT BUMPER GRILLE - CENTER <i>could</i>	1	S	179.00 ✓ 3 sls.
5		FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>could</i>	1	S	332.00 ✓
6		FRONT BUMPER CLOSING ELEMENT (LH/RH) <i>1H could</i>	2	S	636.00 ✓ 318 sls.
7		RADIATOR GRILLE <i>could</i>	1	S	1,406.00 ✓
8		RADIATOR CLOSING ELEMENT <i>could</i>	1	S	210.00 ✓ sls.
9		SECOND STICKER	1	S	9.00 -
10		CAUTION STICKER	1	S	16.00 -
11		FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	S	420.00 ✓
12		FRONT BUMPER FOAM FILLER PIECE <i>could</i>	1	S	211.00 ✓ 3 sls.
13		FRONT BUMPER REINFORCEMENT BEAM <i>could</i>	1	S	847.00 ✓
14		FRONT BUMPER REINFORCEMENT BEAM COVER <i>could</i>	1	S	136.00 ✓
15		HORN - LH / RH	2	S	426.00 ✓
16		BONNET <i>could</i>	1	S	3,370.00 ✓
17		BONNET ATTACHMENT PARTS <i>new</i>	1	S	172.00 ✓
18		BONNET HINGE (LH/RH) <i>could</i>	2	S	136.00 ✓ sls.
19		FRONT FENDER UPPER INNER COVER - LH / RH <i>new</i>	2	S	92.00 ✓
20		BONNET EDGE PROTECTION <i>new</i>	1	S	31.00 ✓ sls.
SUB TOTAL SPARE PARTS			:	\$	11,056.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NOBA.KHIN@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5LD 7888 X

RTS & PRICES

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET CATCH HOOK UPPER <i>Bent</i>	1	\$ 100.00	✓ <i>Sh.S.</i>
22	BONNET STRIKER - LH / RH <i>new</i>	2	\$ 246.00	✓
23	BONNET CATCH HOOK LOWER <i>Bent</i>	1	\$ 71.00	✓
24	BONNET MICRO-SWITCH - LH / RH	2	\$ 455.00	?
25	BONNET BOWDEN CABLE - CENTER	1	\$ 64.00	?
26	BONNET RELEASE CABLE COVER	1	\$ 11.00	?
27	BONNET SOUND ABSORBER	1	\$ 244.00	?
28	PLENUM CHAMBER <i>new</i>	1	\$ 199.00	✓
29	HEADLIGHT - LH / RH <i>Cracked</i>	2	\$ 10,910.00	✓ <i>Sh.S.</i>
30	LIFT CYLINDER - LH / RH <i>new</i>	2	\$ 312.00	✓
31	LIFT CYLINDER HOSE <i>new</i>	1	\$ 78.00	✓
32	LOCK CARRIER <i>Rehanded</i>	1	\$ 806.00	✓ <i>Sh.S.</i>
33	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	?
34	A/C CONDENSER <i>Punctured.</i>	1	\$ 569.00	✓
35	ADDITIONAL RADIATOR <i>new</i>	1	\$ 959.00	+
36	RADIATOR BRACKET - UPPER <i>new</i>	2	\$ 90.00	+
37	RADIATOR BUSH - LOWER	2	\$ 22.00	+
38	RADIATOR COOLANT <i>new</i>	6	\$ 282.00	✓ <i>Sh.S.</i>
39	RADIATOR AIR GUIDE - LH / RH <i>torn</i>	2	\$ 56.00	✓
40	RADIATOR SEAL - OUTER RH <i>new</i>	1	\$ 9.00	+

SUB TOTAL SPARE PARTS

: \$ 15,504.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5LD 7888 X

SPARE PARTS & PRICES			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	USE OF LABS	REMARKS
41	RADIATOR AIR GUIDE - UPPER CENTER ?	1	\$ 14.00		?
42	WINDSCREEN WATER DEFLECTOR STRIP - LH / RH <i>As w</i>	2	\$ 150.00		+
43	FRONT NO PLATE <i>As</i>	S/N	\$ 100.00		✓
44	SUNDRIES ?		\$ 300.00		?
TOTAL SPARE PARTS		:	\$ 27,124.00		
TOTAL LABOUR CHARGES		:	\$ 12,952.00		
GRAND TOTAL		:	\$ 40,076.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.