

Section A - Accident Details

Registration Number	SHD6268P
Case Reference Number	TAX/01/22/2052
Registration Date	28/6/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	FOO JI WEI (FU JIWEI)
Type of Accident	Head to Rear
Accident Date and Time	24/1/2022 9:25 AM
Accident Reported Date and Time	24/1/2022 11:43 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24113788
Special Instruction to ARC, if any	TP/ REAR PORTION
Prepared Date and Time	24/1/2022 3:50 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,296.00	\$200.00
Total Spare Part Cost	\$3,621.68	\$0.00
Total Other Cost	\$520.00	(\$100.00)
TOTAL COST	\$5,944.68	\$300.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	25/01/2022 3:45 PM	25/01/2022 2:41 PM
Signature		
Remarks		LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO .

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2202-0054	Invoice Number	
Quotation Date	09.02.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,296.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$100.00)
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
Total Other Costs	\$520.00	(\$100.00)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair
		90467-07211	BUMPER CLIPS	0.00	\$2.10	0.00	\$0.00	Replace	Not Given
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Not Given
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		89997-30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given

R
X
X
X
X
X
X
X
X
X
X
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/02/2022

User ID : PohSuan

	76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X
	67005-47241	TAILGATE ASY	0.00	\$1,007.90	0.00	\$0.00	Replace	Not Given	X
	67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Not Given	X
	76801-47070-B0	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given	X
	75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
	75442-47030	NAME PLATE (PRUIS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given	X
	75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X
		SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Not Given	X
Total				\$4,708.70		\$0.00			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	0.00	
+	200.00	
+	200.00	
	<u>400.00</u>	L/S \$300/-
	<u>-20%</u>	
	320.00	