

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 10/02/2022

User ID PohSuan

Section A - Accident Details

Registration Number	SHB1013B
Case Reference Number	TAX/01/22/2050
Registration Date	28/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN CHUAN SENG
Type of Accident	Side Swipe
Accident Date and Time	23/1/2022 12:40 AM
Accident Reported Date and Time	24/1/2022 10:26 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24113786
Special Instruction to ARC, if any	TOWED \$40/ TP /RIGHT FRONT PORTION
Prepared Date and Time	24/1/2022 2:31 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$1,656.00	\$400.00
Total Spare Part Cost	\$12,908.23	\$4,142.06
Total Other Cost	\$716.00	(\$942.06)
TOTAL COST	\$15,956.23	\$3,900.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Boon Chew Tay	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	27/01/2022 9:43 AM	27/01/2022 9:02 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP = 0 day.	LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2202-0077	Invoice Number	
Quotation Date	10.02.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$676.00	\$300.00
Total Labour	\$676.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY SIDE PANEL	\$180.00	\$0.00
TO RESPRAY RADIATOR SUPPORT LOWER	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,656.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$972.06)
TOWING CHARGE	\$56.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO ALIGN BODY CHASSIS	\$120.00	\$0.00
Total Other Costs	\$716.00	(\$942.06)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5211947962	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
		5211547050	SUPPORT, FR BUMPER RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace
		5211647050	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given
		5212747907	COVER, FR BUMPER RH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given
		5212847906	COVER, FR BUMPER LH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given
		5202147110	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Not Given
		5261147140	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Not Given
		5210347010	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given
		5210247020	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given

✓
✓
X
X
X
X
X
X
X
X

