

Date: 24.01.2022
Vehicle No: SKR189P
Model: TESLA MODEL 3 PERFORMANCE
Chassis: LRW3F7EC8MC385543
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SMT2219P
Date of Accident: 22.01.2022
Estimator: Victor
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR RH	1		\$1,009.35
SUB TOTAL				\$1,009.35
LESS 10%				-\$100.94
PARTS TOTAL				\$908.42

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	CERAMIC COATING	1	(A11)	\$500.00
S/N TOTAL				\$500.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & READJUST ACCIDENT AREA.

\$400.00

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA.

\$400.00

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$150.00 X

TO DIAGNOS FAULT CODE & RESET MEMORY.

\$200.00 X

LABOUR TOTAL \$1,150.00

TOTAL \$2,558.42

Not when
Paying After Paint
2 days
\$560/h

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Head office

Branch

Branch (Motor Insurance Claims)

6 Kung Chong Road Singapore 159143

9A Serangoon North Ave 5 Singapore 554500

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Tel: (+65) 6484 0919 | Fax: (+65) 6481 1993

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

