

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial PK 2 Singapore 569541
Tel : 64817221

Fax : 64816131

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SMR 3053 D
Make/Model : Toyota Noah
Year : 2019

*Not Withain
1/1000 & 6500
Paying After Pain
6 days*

| Qty | Description | Unit Price | Amount |
|-----|-------------|------------|--------|
|-----|-------------|------------|--------|

Estimate Cost Of Repair

| | | | |
|-------|-------------------------------------------------------|--|--|
| 1 pc | Rear tail-gate | | |
| 1 pc | Rear tail-gate inner trim board | | |
| 1 pc | Rear tail-gate outer chrome handle | | |
| 1 pc | Rear tail-gate glass moulding | | |
| 1 pc | Rear tail-gate emblem " Hybrid " | | |
| 1 pc | Rear tail-gate inner lock | | |
| 1 pc | Rear tail-gate inner lock sensor | | |
| 1 pc | Rear antenna sensor | | |
| 1 pc | Rear boot rubber | | |
| 2 pcs | Rear tail-lamp (LED) <i>781.0155m</i> | | |
| 2 pcs | Rear no plate lamp | | |
| 2 pcs | Rear fender inner trim board <i>n/s xmt</i> | | |
| 2 pcs | Rear tail-lamp lower garnish <i>n/s n/d/Bu</i> | | |
| 1 pc | Rear end panel | | |
| 1 pc | Rear end panel inner garnish | | |
| 1 pc | Rear boot floor panel | | |
| 1 pc | Rear boot floor panel top cover board | | |
| 2 pcs | Rear boot floor panel side cover board <i>1107.60</i> | | |
| 1 pc | Rear bumper - colour code <i>1021.30</i> | | |
| 1 pc | Rear n/s bumper reflector | | |
| 1 pc | Rear bumper tow cover | | |
| 2 pcs | Rear bumper side retainer | | |
| pc | Rear spare tool compartment cover | | |
| pc | Rear air con blower | | |

Less 25 %
balance c/f

\$11,214.15

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMN 3053 D

S Nett

balance b/f \$11,214.15

1 pc Rear reverse camera
1 pc Rear tail-gate glass sealant
20 pcs Rear bumper clip
1 pc Rear reverse sensor

in \$400.00 X
rec \$40.00 ✓
rec \$40.00 ✓
rec \$200.00 ✓
\$680.00

Labour charges

Remove/renew the above parts including knocking, welding & cutting.
To putty and spray paint
Check and reconnect wiring
To respray anti-rust proofing treatment
Remove/refit rear windscreen to facilitate repair
Remove/refit rear tail-gate mechanism to new door.
Remove/renew air con blower & to top up gas.
Remove/refit rear boot upholstery to facilitate repair.

\$1,500.00 *60d*
\$1,500.00 *900d*
\$40.00 *20d*
\$150.00 *60d*
\$120.00 ✓
\$100.00 *60d*
nn \$250.00 X
\$150.00 *100d*
\$15,704.15

Total