

Denise

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SNB8264B

Make & Model: Mercedes Benz B180

Chassis number: WDD2462422J290504

2014

No.	Description of spare parts	Qty	Amount
1	Front bumper	1	\$ 1360.40 1,481.20
2	Front bumper RH chrome moulding	1	\$ 78.45
3	Front bumper LH chrome moulding	1	\$ 78.45
4	Front bumper RH side retainer	1	\$ 28.00 58.65
5	RH headlamp assy	1	\$ 2359.60 2,740.55
6	RH front fender	1	\$ 650.00 691.85
7	RH front fender splash shield (front)	1	\$ 198.00 267.55
8	RH front fender splash shield (rear)	1	\$ 173.00 221.10
9	RH side mirror assy	1	\$ 942.10
10	RH front sport rim	1	\$ 780.00 868.54
11	RH front lower arm	1	\$ 392.00 558.15
12	RH front shock absorber	1	\$ 455.80 783.15
13	RH front knuckle arm	1	\$ 687.40 955.74
14	RH front wheel bearing	1	\$ 181.92
15	RH front tie rod end	1	\$ 109.00
16	RH front drive shaft	1	\$ 1,132.00
17	Steering rack and pinion	1	\$ 2,842.55
18	RH front door	1	\$ 1615.90 1,948.41
19	RH front door weatherstrip	1	\$ 288.00 305.97
20	RH front door lock	1	\$ 302.50 483.00
21	RH front door upper hinge	1	\$ 143.00
22	RH front door lower hinge	1	\$ 143.00
23	RH front door checker stopper	1	\$ 154.00
24	RH front door chrome moulding	1	\$ 143.50 233.00
25	RH front door glass regulator gear	1	\$ 294.00
26	RH front door glass regulator gear motor	1	\$ 475.00 627.00
27	RH front door speaker	1	\$ 137.00
28	RH side rocker panel garnish	1	\$ 599.38
29	RH rear door	1	\$ 1801.00 1,970.52
30	RH rear door upper hinge	1	\$ 143.00
31	RH rear door lower hinge	1	\$ 143.00
32	RH rear door checker stopper	1	\$ 154.00

BRV
 } NECV
 BRV
 DDV
 DISV
 DLV
 BRV
 CUTV
 BTV
 BTV
 DDV
 JMV
 BTV
 NDX
 NDX
 DDV
 ?NECV
 JMV
 } BTV
 NSX
 BTV
 } JMV
 ?NDX
 NDX
 DDV
 } NDX
 NSX

Spare Parts:	\$	32,991.40
Special Nett:	\$	700.00
Labour:	\$	6,400.00
Total Amount:	\$	40,091.40

Survey	Resurvey
11/2/2022	23/2/2022
1508 hrs	1550 hrs
TCUim Min	TCUim Min

Lump sum repair
Repair days 10

Parts	14,718.40
Labour	6,400.00
Special Nett	700.00
	21,818.40
	19,218.40

TCUim Min
2/3/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Parts price revised and Supplementary

Vehicle number: SNB8264B

Make & Model: Mercedes Benz B180

No.	Description of spare parts	Qty	Amount
1	Bonnet	1	\$ ✓ 1,475.00
2	RH taillamp assy	1	\$ 544.00 859.00
		Total	\$ 2,334.00
		Less 10%	\$ 233.40
		Total	\$ 2,100.60

DDV
BRU

No.	Description of spare parts (Special Nett)	Qty	Amount

No.	Labour		Amount
1	Labour		\$ -350.00
2	Spray painting bonnet		\$ 250.00

}NNX

Total Amount

\$

2,700.60

Resurvey
24/2/2022
Train hi
1340 hrs

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: