

ASS. REC. BY: TGLum

REF:

CS/CT12200919/Bny3

Denise

ASSIGNMENT

From: _____ Date: 11/2/2022

Veh No: SNB 8264B Yr Regn: 2/12/2014

Estimated Cost: _____

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: SNB 8264B

Make: Mercedes Benz B180 c.c 1595

at Workshop m/s Bifrost Auto

Colour: Silver A/C: Insured / Std / NI / NA

of 8 Kaki Bukit Ave 4 Premier # 01-49

Sp. Reading: 128154 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: 27091030516979

Policy No. _____

C/No: WDD2462422J290504

Claims No. _____

Gen. Cond: Good / Fair / ~~Poor~~ / Burnt

Sum Insured: _____ Excess: _____

Steering: ~~In order~~ / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ~~In order~~ / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / ~~SRim~~ / STD A/Rim or

(Policy Condition)

Tyre Size: F: 205/55/16

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

R: 205/55/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Bal. or Market Value: 48,000/2

Front Rear

IDAC Accident Rpt: _____ Consistent? : Yes or No

R/Bal. 5 mm

GIA / PR Seen: _____ Consistent? : Yes or No

L/Bal. 5 mm

Est. Repairs: 10 days Res.: Yes or No

D.O.A. 23/1/2022 D.O.I. 11/2/2022

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at Bifrost Auto

CA / REV / REP. / 24 HRS ~~WP~~

Des. of Damages: Ft / Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: 17,000/2 - 18,000/2
	Recommended COR: LS \$17,800.00 TGLum 3/2/2022
	7/15K.
	MV 48,000/2
	PV 29,286/2 10/10/22 lump sum 15000 and 10 days TGLum
	NV 18,714/2 (Red, 27792, 65%) 12/2/2022

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 10

1) 10/10/22 : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Add Fee: : Site Insp (\$ _____)

Survey Fee:

2) _____

: Interview (\$ _____)

Transportation: _____ S + RS. _____ SI

Rep. Format: _____

: Tech. Invs (\$ _____)

Photos

Lump Sum / I.B.I. (\$) 15000

: Weekend (\$ _____)

Others

TOTAL

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	771J
Vehicle Details	
Vehicle No.:	SNB8264B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Feb 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B180 (R16 BI)
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	27091030516979
Chassis No.:	WDD2462422J290504
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$25,004.00
Original Registration Date:	02 Dec 2014
First Registration Date:	02 Dec 2014
Transfer Count:	4
Actual ARF Paid:	\$17,006.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Dec 2024
PARF Rebate Amount:	\$10,203.00
Intended COE Rebate Details	
COE Expiry Date:	01 Dec 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,889.00
COE Rebate Amount:	\$19,083.00
Total Rebate Amount:	\$29,286.00

The information contained herein is correct as at 09 Feb 2022

OK

MV 48,000/2
PV 29,286/2
NV 18,714/2

TG Lim
12/2/2022

VEHICLE NO: SNB82648

MAKE & MODEL: MERC B180.

AUTO / MANUAL

DATE OF ACCIDENT	2#3 / 01 / 22.	*CC:
TIME OF ACCIDENT	1400.	AM / PM
LOCATION OF ACCIDENT	15 GOODLANDS LOOP.	
EXACT PURPOSE USED AT TIME OF ACCIDENT	EMPLOYMENT / PRIVATE USE / PRIVATE HIRE	
NAME OF OWNER	HAIRULNIZAM BIN JAMIL.	
EMAIL:	CITIZENPOWER SSS @GMAIL.COM	Office: MOBILE: 88997415.
NRIC	S823071J.	
CLAIM TYPE	OD / THIRD PARTY / REPORTING ONLY	
FLEET POLICY:	YES / NO ?	
INSURANCE CO.	NTC.	
TYPE OF COVERAGE	Comprehensive / Third Party / Third Party Fire & Theft	
POLICY NO.	5124922359.	
NAME OF DRIVER	AS ABOVE / IF NO:	
NRIC	"	
DATE OF BIRTH	15 / 10 / 1982.	
ANY PASSENGER	YES / NO: 4 OTHERS.	
NAME OF PASSENGER	(F) SUB ZANAH BTE JIHAN, (F) NUR IYLIA, (F) NUR ELISSA, (F) AJUL ERINNA.	
GENDER OF PASSENGER	MALE / FEMALE.	
OCCUPATION	Outdoor / Indoor	
DATE OF DRIVING PASS	04 / 03 / 12.	
GENDER	Male / Female	
CONTACT NO.	Mobile: "	Office: Home:
EMAIL:	"	
ADDRESS	690F GOODLANDS DR 75 #03-04 SC736690.	
DOES DRIVER OWN OTHER VEHICLES?	NO. / If yes: Reg No.	INSURER: -
RELATIONSHIP	Employee / If No: SELF.	
WEATHER CONDITION	Clear / Raining / Other:	
ROAD SURFACE	Dry / Wet / Other:	
ANY INJURIES	No / If yes: Who? DRIVER x NUR IYLIA.	
CONTACT NO.		
POLICE REPORT	No / If yes: Where? TP HQ.	
NOTICE OF INTENDED PROSECUTION GIVEN?	NO / IF YES: WHO?	
VEHICLE B NO.	6B15753R.	Any Passenger:
NAME		
CONTACT NO.		
VEHICLE C NO.	Any Passenger:	
VEHICLE D NO.	Any Passenger:	
VEHICLE E NO.	Any Passenger:	
VEHICLE F NO.	Any Passenger:	
ANY WITNESS		
WITNESS CONTACT NO.		
WAS THERE ANY VIDEO CAPTURE?	YES / NO	
WAS THERE ANY AUDIO RECORDED?	YES / NO	
SCENE ACCIDENT PHOTOS TAKEN?	YES / NO	
**WORKSHOP:		
Have you been approach by unknown person soliciting (s) / offering accident claims assistance?	YES / NO	



**SINGAPORE
POLICE FORCE**



T/20220124/7014

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 4

Report No. T/20220124/7014

CONTINUATION OF REPORT

Driver			
Name	HAIRULNIZAM BIN JAMIL		ID No. S8230771J
Related Vehicle	SNB8264B (Car)		Contact No. 88997415
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Class: NIL Date of Expiry: NIL
Date	NIL		Date NIL
No. of Days granted Medical Leave	03	Degree of	Serious
Passenger			
Name	SUZANAH BTE JOHAN		ID No. S7819413H
Related Vehicle	SNB8264B (Car)		Contact No. 87790867
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Class: NIL Date of Expiry: NIL
Date	NIL		Date NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
Passenger			
Name	NUR ERYNNA		ID No. NIL
Related Vehicle	SNB8264B (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Class: NIL Date of Expiry: NIL
Date	NIL		Date NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
Passenger			
Name	NUR ELYSSA		ID No. NIL
Related Vehicle	SNB8264B (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Class: NIL Date of Expiry: NIL
Date	NIL		Date NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL



**SINGAPORE
POLICE FORCE**



T/20220124/7014

3 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20220124/7014

CONTINUATION OF REPORT

Passenger			
Name	NUR IYLIA BINTE HAIRULNIZAM		ID No. T0927798B
Related Vehicle	SNB8264B (Car)		Contact No. 88997415
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	03	Degree of	Serious

Brief Details.

ON THE STATED DATE AND TIME, I WAS TRAVELLING STRAIGHT. OUT OF NOWHERE, I SAW GBJ5953R COMING INTO MY LANE FROM THE OPPOSITE LANE. I TRIED TO AVOID THE COLLISION BUT I WAS VERY CLOSE TO THE KERB ON MY LEFT AND COULDNT MOVE TO THE LEFT ANYMORE. GBJ5953R CONTINUED TO APPROACH MY VEHICLE AND HIT MY VEHICLE FROM THE FRONT PORTION OF MY VEHICLE TO THE REAR.

THERE WERE 5 PEOPLE IN MY VEHICLE INCLUDING MYSELF.

MYSELF AND MY DAUGHTER WHO WAS SEATED THE NEAREST TO THE ACCIDENT PORTION WENT TO SEEK FOR PROFESSIONAL MEDICAL HELP AS WE FELT PAIN AFTER THE ACCIDENT AND WERE GIVEN 3 DAYS OF MC EACH.

Denise

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SNB8264B
 Make & Model: Mercedes Benz B180
 Chassis number: WDD2462422J290504

2014

No.	Description of spare parts	Qty	Amount
1	Front bumper	1	\$ 1360.40 1,481.20
2	Front bumper RH chrome moulding	1	\$ 78.45
3	Front bumper LH chrome moulding	1	\$ 78.45
4	Front bumper RH side retainer	1	\$ 28.00 58.65
5	RH headlamp assy	1	\$ 2359.60 2,740.55
6	RH front fender	1	\$ 650.00 691.85
7	RH front fender splash shield (front)	1	\$ 198.00 267.55
8	RH front fender splash shield (rear)	1	\$ 173.00 221.10
9	RH side mirror assy	1	\$ 942.10
10	RH front sport rim	1	\$ 700.00 868.54
11	RH front lower arm	1	\$ 392.00 558.15
12	RH front shock absorber	1	\$ 455.80 783.15
13	RH front knuckle arm	1	\$ 687.40 955.74
14	RH front wheel bearing	1	\$ 181.92
15	RH front tie rod end	1	\$ 109.00
16	RH front drive shaft	1	\$ 1,132.00
17	Steering rack and pinion	1	\$ 2,842.55
18	RH front door	1	\$ 1615.90 1,948.41
19	RH front door weatherstrip	1	\$ 288.00 305.97
20	RH front door lock	1	\$ 302.50 483.00
21	RH front door upper hinge	1	\$ 143.00
22	RH front door lower hinge	1	\$ 143.00
23	RH front door checker stopper	1	\$ 154.00
24	RH front door chrome moulding	1	\$ 143.50 233.00
25	RH front door glass regulator gear	1	\$ 294.00
26	RH front door glass regulator gear motor	1	\$ 475.00 627.00
27	RH front door speaker	1	\$ 137.00
28	RH side rocker panel garnish	1	\$ 599.38
29	RH rear door	1	\$ 1801.00 1,970.52
30	RH rear door upper hinge	1	\$ 143.00
31	RH rear door lower hinge	1	\$ 143.00
32	RH rear door checker stopper	1	\$ 154.00

BRV
 } NECV
 NECV
 BRV
 DDV
 DISV
 DLV
 BRV
 CUTV
 BTU
 BTU
 DPV
 JMV
 BTU
 NDX
 NDX
 DDV
 ?NECV
 JMV
 } BTU
 NSX
 BTU
 } JMV
 ?NDX
 NDX
 DDV
 } NDX
 NSX

		Total	\$ 700.00

	Labour and painting		Amount
			1400.00
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas		\$ 1600.00 2,000.00 ✓
2	Spray painting on affected areas and panels		\$ 1400.00 1,600.00 ✓
3	Check wiring and lighting system		\$ 50.00 100.00 ✓
4	Apply rust coating chemical on affected areas and panels		\$ 80.00 180.00 NNX
5	Test drive and adjust wheel alignment system		\$ 60.00 100.00 ✓
6	Remove and replace front undercarriage parts to assist repair		\$ 200.00 550.00 ✓
7	Remove and replace RH front door inner mechansim to new door		\$ 80.00 180.00 ✓
8	Remove and replace RH rear door inner mechansim to new door		\$ 80.00 180.00 ✓
9	Remove and replace RH side door piilar inner trims, garnish, carpet, roof lining, boards and seat belts to assist repair		\$ 60.00 450.00 NNX
10	Remove and replace rear undercarriage parts to assist repair		\$ 380.00 380.00 NNX
11	Remove and reinstall rear bumper reverse sensors to assist repair		\$ 60.00 100.00 ✓
12	Remove and reinstall RH rear fender glass to assist repair		\$ 80.00 180.00 NNX
13	Remove and replace front and rear seat belts and buckles to assist repair		\$ 400.00 400.00 NNX
		Total	\$ 6,400.00

Spare Parts:	\$	32,991.40
Special Nett:	\$	700.00
Labour:	\$	6,400.00
Total Amount:	\$	40,091.40

Survey	Resurvey
11/2/2022	23/2/2022
1508 hrs	1550 hrs
TCUim Mui	TCUim Mui

Lump sum repair
 Repair days 10

TCUim Mui
 2/3/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

42792

Total Amount

\$

2,700.60

Resurvey

24/2/2022

Train hi

1340 hrs

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: