

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Parts price revised and Supplementary

Vehicle number: SNB8264B

Make & Model: Mercedes Benz B180

No.	Description of spare parts	Qty	Amount
1	Bonnet	1	\$ ✓ 1,475.00
2	RH taillamp assy	1	\$ 544.00 859.00
		Total	\$ 2,334.00
		Less 10%	\$ 233.40
		Total	\$ 2,100.60

DDV
BRU

No.	Description of spare parts (Special Nett)	Qty	Amount

No.	Labour		Amount
1	Labour		\$ -350.00
2	Spray painting bonnet		\$ 250.00

}NNX

Total Amount

\$

2,700.60

Resurvey
24/2/2022
Train hi
1340 hrs

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: