5/11/23, 11:45 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22000922/UPA3Q2

11/05/2023 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993593 **Claimant Vehicle** 

SFM7887Y Insured Vehicle No: GBL972H No:

Date of Loss: 25/01/2022 Nature of Claim: TP Claim No: 7531929468SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SFM7887Y

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) 1ZRY296845 Engine No:

Reg. Date: 29/08/2016 (Man. Year: 2016) Chassis No: MR053REH104551882

Odometer: Colour: Black 262844 km

**Engine Capacity:** 1598 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/45Z R17 215/45Z R17 Rear Tyre Size: Front Left Side: CST 6 mm Rear Left Side: CST 6 mm Front Right Side: CST 6 mm Rear Right Side: CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,706.40	1,373.10	3,333.30	70.82
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,630.00	880.00	1,750.00	66.54
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	7,336.40	2,253.10	5,083.30	69.29
	Approved Total (Overridden) (S\$)		1,800.00		
	(S\$)	7,336.40	1,800.00	5,536.40	75.46
	+ GST 7.00/7.00% (S\$)	513.55	126.00	387.55	75.46
	Nett Amount (S\$)	7,849.95	1,926.00	5,923.95	75.46
	+ Loss of Use (2.0 x S\$	660.00/day) (S\$)	120.00		
	+ Doc/S	Search Fee (S\$)	7.45		
	Ne	ett Liability (S\$)	2,053.45		
	Global Sum	Settlement (S\$)	2,050.00		

**INSPECTION** 

Date of Assignment: 26/01/2022

Fastech Auto Pte Ltd (HQ)

Date Inspected: 26/01/2022 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Inspected At:

Singapore 417883

Estimated Period of Repair: 2.0 days

**CHEW HSIAO TONG** Adjuster: MARCUS CHUA Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	655.10 F	*486.50 FL
2	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	65.00 F	*- FL
3	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
4	1		*REAR BUMPER REFLECTROR O/S	Scratched	68.10 F	*48.10 FL
5	1		*REAR BUMPER SIDE GUIDE O/S	Scratched	98.10 F	*66.80 FL
6	1		*REAR FENDER O/S	Repair	1,091.10 F	*- FL
7	1		*REAR FENDER SPLASH SHIELD O/S	Not Necessary	145.80 F	*- FL
8	1		*REAR SPORT RIM O/S	Warped	980.50 FS	*600.00 FS
9	1		*TAILLAMP O/S	Scratched	580.00 F	*379.40 FL
10	1		*REAR SHOCK ABSORBER O/S	Not Necessary	322.10 F	*- FL
11	1		*REAR WHEEL HUB BEARING O/S	Not Necessary	650.60 F	*-FL
r=rra	inchise	part. 5=5pciv	ett. L=ListItemDisc.	Sub Total (S\$)	4,706.40	1,630.80
	- List Item Discount on L Items 0.00/25.00% (S\$)				0.00	257.70
				Total Parts (S\$)	4,706.40	1,373.10
			Report was unsubmitted du	uring this print-out.		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	40.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	60.00
4	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
5	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	New	250.00	0.00
6	TO SPRAY RUST PROOFING	New	50.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	880.00	300.00
8	TO PUTTY & SPRAY PAINTING	New	1,080.00	400.00
	Gros	s Labour Cost (S\$)	2,630.00	880.00
	Report was unsubmitted du	uring this print-out.		

< END OF ESTIMATES >