

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

not allowed
 20/1/22
 1/5 #1800
 2 days.

VEHICLE No: SFM 7887Y

1PC	REAR BUMPER	Re	486.50	\$655.10	—
1PC	REAR BUMPER SIDE RETAINER O/S	11		\$65.00	X
1SET	REAR BUMPER CLIPS	Re		\$50.00	—
1PC	REAR BUMPER REFLECTOR O/S	scn	48.10	\$68.10	—
1PC	REAR BUMPER SIDE GUIDE O/S	scn	66.80	\$98.10	—
1PC	REAR FENDER O/S	R		\$1,091.10	X
1PC	REAR FENDER SPLASH SHIELD O/S	11		\$145.80	X
1PC	REAR SPORT RIM O/S	margin		\$980.50	— 600 s/w
1PC	TAILLAMP O/S	scn	(25%) 379.40	\$580.00	—
1PC	REAR SHOCK ABSORBER O/S	11		\$322.10	X
1PC	REAR WHEEL HUB BEARING O/S	11		\$650.60	—
				\$4,706.40	

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$80.00	40
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	60
TO CONDUCT WHEEL ALIGNMENT	\$120.00	60
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	11 \$250.00	X
TO SPRAY RUST PROOFING	11 \$50.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$880.00	300
TO PUTTY & SPRAY PAINTING	\$1,080.00	400
TOTAL	\$7,336.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date:

P- 1030.80
 25%
 7- 773.1
 SA- 600
 L- 880
 223.1
 2.2
 1802