



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authorized

27 January 2022

2000
26/1/22

2/5 \$ 9800/

6 days

Telephone Afternoon

REG NO.: SNA 5110 L
MAKE/MODEL: BMW 523i

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front bonnet	2,292.00 X
2	Front bonnet dampers	270.00 X
2	Front bonnet hinges	230.00 X
1	Front bonnet lock	210.00 X
1	Front bonnet rubber	42.00 X
2	Front headlamps	9,241.40 ✓
2	Front headlamp lower brackets	226.00 X
2	Front grilles	370.00 ✓
1	Front bumper	1,578.90 ✓
2	Front bumper brackets	210.00 X
1	Front bumper air guide	153.00 ✓
2	Front bumper fog lamps	490.00 X
1	Front bumper inner foam	128.00 ✓
1	Front bumper centre lower grille	68.00 ✓
2	Front bumper side grilles	108.00 ✓
2	Front bumper side grille mouldings	64.00 X
1	Front bumper logo	59.00 ✓
1	Front bumper lower beam	145.00 X
1	Front bumper reinforcement	719.00 ✓
2	Front bumper reinforcement stays	300.00 ✓
2	Front bumper side retainers	258.00 X
1	Front bumper top rubber seal	90.00 ✓
1	Front bumper tow hook cover	40.00 X
2	Front bumper nozzle covers	136.00 X
2	Front bumper nozzle motor assy	390.00 X
4	Front bumper PDC sensors	1,260.00 120
1	Front support panel	850.00 ✓
1	Front support panel top garnish	100.00 ✓
2	Front support panel side garnishes	240.00 X
1	Front support panel stay	115.00 X
1	Air con condenser	1,185.00 ✓
1	Radiator	1,685.00 X
		\$ 23,253.30
	Less 5%	\$ 1,162.67
		\$ 22,090.64

SPECIAL NETT ITEMS

- 1 Front bumper clip (1 set) *Net*
- 1 Front number plate with holder *300*

\$	80.00	<i>50</i>
\$	80.00	<i>40</i>
\$	130.00	

S.N

LABOUR CHARGES

- 1 To check wiring and reset headlamps focusing.
- 2 To remove and refit front sensor.
- 3 To remove, replace air-con condenser, refill gas & conduct leakage test.
- 4 To apply undercoating.
- 5 Panel beating.
- 6 To re-spray painting on the affected areas.
- 7 To diagnose erase fault memory after repair.

\$	80.00	<i>20</i>
\$	180.00	<i>50</i>
\$	180.00	<i>100</i>
\$	200.00	<i>X</i>
\$	1,800.00	<i>800</i>
\$	1,800.00	<i>550</i>
\$	300.00	<i>X</i>
\$	4,340.00	

GRAND TOTAL :

\$	20,580.84
----	-----------

The undersigned hereby certify that the above
particulars are correct and true.
= To check wiring and reset headlamps focusing
= To remove and refit front sensor
= To remove, replace air-con condenser, refill gas & conduct leakage test
= To apply undercoating
= Panel beating
= To re-spray painting on the affected areas
= To diagnose erase fault memory after repair
Approved by the undersigned
Signature
Date

P-11319.42
52
P-10753.44
S.N-90
K-1520