

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

SNA5110C

at Workshop m/s

200m

of

Insured: SLT 8224X

Policy No. 30001962056

Claims No. 268846

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$ 70k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

02796

Veh No:

SNA5110C

Yr Regn:

16/8/10

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAI

Make:

*BMW**523i*

c.c.

2497

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

256882

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAFP 32030C545335

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45-218

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

24/1/22

D.O.I.

20/1/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*coe ul. 15-8-2030 17A & 28153**CNY 1-2-22**26/2/22**4/5 & 8805 8900 informed Elin*

(red 17,660.64, 66%)

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

6

1)

☐

Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2) 28/2/22-typist

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

Report Format: Merimen

Lump Sum / t.B.: (\$ 8900

TOTAL



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

27 January 2022

REG NO.: SNA 5110 L
MAKE/MODEL: BMW 523i

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	LIST ITEMS	
1	Front bonnet	2,292.00 X
2	Front bonnet dampers	270.00 X
2	Front bonnet hinges	230.00 X
1	Front bonnet lock	210.00 X
1	Front bonnet rubber	42.00 X
2	Front headlamps	9,241.40 X
2	Front headlamp lower brackets	226.00 X
2	Front grilles	370.00 X
1	Front bumper	1,578.90 X
2	Front bumper brackets	210.00 X
1	Front bumper air guide	153.00 X
2	Front bumper fog lamps	490.00 X
1	Front bumper inner foam	128.00 X
1	Front bumper centre lower grille	68.00 X
2	Front bumper side grilles	108.00 X
2	Front bumper side grille mouldings	64.00 X
1	Front bumper logo	59.00 X
1	Front bumper lower beam	145.00 X
1	Front bumper reinforcement	719.00 X
2	Front bumper reinforcement stays	300.00 X
2	Front bumper side retainers	258.00 X
1	Front bumper top rubber seal	90.00 X
1	Front bumper tow hook cover	40.00 X
2	Front bumper nozzle covers	136.00 X
2	Front bumper nozzle motor assy	390.00 X
4	Front bumper PDC sensors	1,260.00 X
1	Front support panel	850.00 X
1	Front support panel top garnish	100.00 X
2	Front support panel side garnishes	240.00 X
1	Front support panel stay	115.00 X
1	Air con condenser	1,185.00 X
1	Radiator	1,685.00 X
		23,253.30
	Less 5%	1,162.67
		22,090.64

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	\$	80.00	50
1	Front number plate with holder	\$	50.00	40
		\$	130.00	

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00	20
2	To remove and refit front sensor.	\$	180.00	50
3	To remove, replace air-con condenser, refill gas & conduct leakage test.	\$	180.00	100
4	To apply undercoating.	\$	200.00	X
5	Panel beating.	\$	1,800.00	800
6	To re-spray painting on the affected areas.	\$	1,600.00	550
7	To diagnose erase fault memory after repair.	\$	300.00	X
		\$	4,340.00	

GRAND TOTAL :**\$ 26,560.64**

LKK Auto Consultants, hence notify the Repainer of the following:

- To resurvey below-water spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repainer:

Signature:

Date:

10060.72
 596.
 9557.08
 1-11319.42
 52
 2-10753.44
 S.N - 90
 L - 1520