

Shiau Chan (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Wednesday, 23 February 2022 1:18 PM
To: Shiau Chan (LKKAuto)
Subject: RE: III-TP SKX 5835T SURVEYED BY KENNETH (OUR REF: CS/GRB22000925/Kqf3)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SKX5835T, FOUND UNDERCARRIAGE PARTS REPLACED WITHOUT WHEEL ALIGNMENT REPORT.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 23 February, 2022 12:09 PM
To: Simon Ho (LKKAuto)
Subject: RE: III-TP SKX 5835T SURVEYED BY KENNETH (OUR REF: CS/GRB22000925/Kqf3)

Dear Simon,

For your re-audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Sent: Monday, 7 February 2022 11:51 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: III-TP SKX 5835T SURVEYED BY KENNETH (OUR REF: CS/GRB22000925/Kqf3)

Dear Shiau Chan,

Audit check done for SKX5835T, found some parts prices need verification.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto)

Sent: Thursday, 3 February, 2022 2:48 PM

To: Simon Ho (LKKAuto)

Subject: III-TP SKX 5835T SURVEYED BY KENNETH (OUR REF: CS/GRB22000925/Kqf3)

Dear Simon,

For your audit.

"Wishing You Happiness & Prosperity Chinese New Year 2022"

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)