

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Feb 2022)
Parts: 143 TOYOTA CAMRY 2.4 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJQ2876T)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER INNER SPONGE ✓ CRA	0.00	0.00	*65.00 F
Sub Total (S\$)						65.00
+ Margin on L,N Items 10.00% (S\$)						6.50
Total Parts (S\$)						71.50

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Parts 5,080

+10% 5,588

SN 320

LC 2550

8,458

L/S 6,750

21/02/2022

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Jan 2022)
Parts: 143 TOYOTA CAMRY 2.4 L (A) (Catalogue: Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJQ2876T)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF, ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT / <i>buc</i>	0.00	0.00	*380.00 F
2	2		*REAR BOOT HINGES <i>BT</i>	0.00	0.00	*130.00 F
3	1		*REAR BOOT CENTRE LOGO <i>BT</i>	0.00	0.00	*40.00 F
4	1		*REAR BOOT CAMRY PLATE <i>MC</i>	0.00	0.00	*35.00 F
5	1		*REAR BOOT 2.4 PLATE <i>MC</i>	0.00	0.00	*35.00 F
6	1		*REAR BOOT OUTER MOULDING <i>le</i>	0.00	0.00	*175.00 F
7	1		*REAR BOOT LOCK <i>BT</i>	0.00	0.00	*150.00 F
8	1		*REAR BOOT INNER RUBBER <i>Tri</i>	0.00	0.00	*75.00 F
9	2		*REAR BOOT LAMP <i>CAH</i>	0.00	0.00	*300.00 F
10	1		*REAR BUMPER <i>le</i>	0.00	0.00	*240.00 F
11	2		*REAR BUMPER RETAINER <i>X NN</i>	0.00	0.00	*70.00 F
12	10		*REAR BUMPER CLIPS <i>MC</i>	0.00	0.00	*20.00 F
13	2		*REAR BUMPER REFLECTOR <i>CRA</i>	0.00	0.00	*70.00 F
14	1		*REAR BUMPER REINFORCEMENT <i>?</i>	0.00	0.00	*160.00 F
15	2		*REAR TAIL LAMP <i>CAH</i>	0.00	0.00	*360.00 F
16	1		*REAR END PANEL <i>BT</i>	0.00	0.00	*230.00 F
17	1		*REAR END PANEL TOP GARNISH <i>le</i>	0.00	0.00	*150.00 F
18	4		*TOP GARNISH CLIPS <i>MC</i>	0.00	0.00	*8.00 F
19	2		*REAR TAIL LAMP PANEL <i>?</i>	0.00	0.00	*150.00 F
20	4		*REAR TAIL LAMP CLIPS <i>MC</i>	0.00	0.00	*24.00 F
21	1		*FRT GRILLE <i>CAH</i>	0.00	0.00	*165.00 F
22	1		*GRILLE CENTRE LOGO <i>MC</i>	0.00	0.00	*40.00 F
23	4		*GRILLE CLIPS <i>MC</i>	0.00	0.00	*8.00 F
24	1		*FRT BUMPER <i>le</i>	0.00	0.00	*220.00 F
25	2		*FRT BUMPER RETAINER <i>X NN</i>	0.00	0.00	*64.00 F
26	10		*FRT BUMPER CLIPS <i>MC</i>	0.00	0.00	*20.00 F
27	1		*FRT BUMPER REINFORCEMENT <i>BT</i>	0.00	0.00	*165.00 F
28	2		*FRT BUMPER MOULDING	0.00	0.00	*90.00 F
29	2		*HEADLAMP <i>CAH</i>	0.00	0.00	*990.00 F
30	1		*HEADLAMP SUPPORT PANEL <i>X repair</i>	0.00	0.00	*330.00 F
31	1		*BRACE PANEL <i>X NN</i>	0.00	0.00	*55.00 F
32	1		*AIRCON CONDENSER <i>?</i>	0.00	0.00	*530.00 F

F=Franchise part.

Sub Total (\$\$) *5015* 5,479.00
+ Margin on L,N Items 10.00% (\$\$) 547.90
Total Parts (\$\$) *5516.50* 6,026.90

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

flr buy in sponge \$65.

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRT NUMBER PLATE	1 BT	35.00
2	1	RADIATOR COOLANT	1 BT	25.00
3	1	REAR NUMBER PLATE	1 BT	35.00
4	1	REVERSE SENSOR	1 Om	250.00

200 250.00

Sub Total (S\$) 345.00

270 ~~220~~

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	WIRE CHECKING	New	30.00	1
2	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00	60
3	CAVITY PROTECTION ON ALL AFFECTED AREAS	New	150.00	60
4	REMOVE & REFIX AIRCON AND GAS	New	100.00	7
5	LABOUR CHARGE	New	1,800.00	80
6	SPRAY PAINTING	New	1,400.00	

Gross Labour Cost (S\$) 3,600.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

2550

< END OF ESTIMATES >

9 Days.

L/s

After repair photos.

Guo Ai ng - 82880282

08/2/22