



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

QBE INSURANCE (S) PTE LTD

INV No. AC2202891

1 RAFFLES QUAY #29-10 SOUTH TOWER
SINGAPORE 048583

INV Date 19/05/2022
Reference CC3/QBE22000930/Eea3q2
Code QBE

PROFESSIONAL SERVICE FEE

Vehicle No. SCN 8119E
Insured Veh. GX 3663H
Claim No. ACVC014979
Policy No. 8-XM108791-MVA-R017
Accident Date 23/01/2022
Inspection Date 25/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (S) PTE LTD 1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Ref: CC3/QBE22000930/Eea3q2	
			Date: 19/05/2022	
			Code: QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GX 3663H	Veh. Inspected	SCN 8119E
	Policy No.	8-XM108791-MVA-R017	Coverage (\$)	0.00
	Claim No.	ACVC014979	Excess (\$)	0.00
	Assign From		Assign Date	25/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN SUNNY	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	JN1CFAN16Z0102907	Colour	WHITE
	Odometer	159304 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	FIRESTONE	4 mm
	L/H Front Tyre	185/65 R15	FIRESTONE	4 mm
	R/H Rear Tyre	185/65 R15	FIRESTONE	4 mm
	L/H Rear Tyre	185/65 R15	FIRESTONE	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND INTERIOR. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/01/2022	Inspection Date	25/01/2022
	Survey held at	TAN CHONG MOTOR SALES PTE LTD 911 BUKIT TIMAH ROAD SINGAPORE 589623		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCN 8119E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	MIRROR ASSY CENTER VIEW (N)	BROKEN	153.40	153.40
1	EMBLEM RAD GRIL (N)	NECESSARY	60.60	60.60
8	CLIP ENGINE COVER @\$1.40 (N)	NECESSARY	11.20	11.20
1	COVER -FR UNDER LH LOWER (N)	NOT NECESSARY	89.40	-
1	RUBBER -DUM (N)	NECESSARY	63.80	63.80
1	MLDG ASSY -FR PL (N)	NECESSARY	64.30	64.30
1	MLDG ASSY -FR PL (N)	NECESSARY	64.30	64.30
1	MLDG WS UPPER (N)	NECESSARY	85.70	85.70
1	GLASS -FR WIND (N)	BROKEN	1,068.50	1,068.50
1	MALE ASSY -HOOD (N)	NOT NECESSARY	50.60	-
1	HOOD (N)	DENTED	1,085.50	1,085.50
1	STAY -FR FENDER LH BRACKET (N)	NOT NECESSARY	37.60	-
7	CLIP FENDER @\$1.30 (N)	NECESSARY	9.10	9.10
2	CANOE RIVET FENDER @\$7.80 (N)	NECESSARY	15.60	15.60
2	CANOE RIVET FENDER @\$7.10 (N)	NECESSARY	14.20	14.20
1	PROTECTOR -FR ,LH FENDER (N)	MISSING	129.30	129.30
1	FENDER -FRONT LH (N)	DENTED	593.30	593.30
1	GRILLE -RADIATOR (N)	CUT	245.60	245.60
1	STAY -BUMPER LH (N)	DENTED	106.50	106.50
1	RETAINER BUMPER (N)	DENTED	200.30	200.30
1	REINFORCE -BUMPE (N)	DENTED	354.10	354.10
1	BRKT -BPR SIDE ,LH (N)	BROKEN	28.30	28.30
1	FINISHER -FR ,LH FOG (N)	MISSING	153.50	153.50
1	MOULE-BUMPER CHROME (N)	BROKEN	215.60	215.60
1	BUMPER SET FR (N)	BROKEN	474.10	474.10
1	MODULE ASSY AIRBAG (N)	NECESSARY	2,316.40	2,316.40
1	LAMP ASSY -LH (N)	BROKEN	586.40	586.40
	LESS 20% DISCOUNT		-1,655.44	-1,619.92
			6,621.76	6,479.68



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	WIRE-STEERING AIRBAG (SN)	NECESSARY	238.40	238.40
1	SEALANT -FRONT W/SCREEN GLASS (SN)	NECESSARY	80.00	80.00
1	IU BRACKET (SN)	NECESSARY	26.00	26.00
4	CLIP RADIATOR GRILLE @\$3.40 (SN)	NECESSARY	13.60	13.60
1	WHEEL ASSY -STEE (SN)	NOT NECESSARY	695.00	-
1	CLIP HEADLAMP (SN)	BROKEN	3.80	3.80
1	SENSOR & UNIT -AIR BAG (SN)	BROKEN	822.30	822.30
1	RESONATOR ASSY (SN)	MISSING	136.90	136.90
2	NISSAN SILL COOLANT @\$9.50 (SN)	NECESSARY	19.00	19.00
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			2,135.00	1,370.00
	<u>LABOUR</u>			
	FOCUS & ADJUST H/LAMP ,RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPEFICATION.		48.00	48.00
	RENEW AIR BAG MODULE SENSOR RESET SYSTEM USING NISSAN COSULT.		240.00	240.00
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL .		240.00	120.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.		300.00	200.00
	INSTALL ULTRAMAX SOLAR FILM -FRT W/SCREEN WITH ANTI GLARE.		150.00	150.00
	RENEW FRONT WINDSHIELD GLASS ASSY .		150.00	150.00
	CHECK WHEEL ALIGNMENT ,ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE.		108.00	108.00
	REPAIR LH FRONT DOOR ,LH FRONT WHEELHOUSE AND RENEW BONNET ,LH FRONT FENDER ,SUPPORT PANEL ,FRONT BUMER.		2,730.00	1,560.00
	S/PAINT FRONT BUMPER ,LH FRONT FENDER ,DOOR ,SUPPORT PANEL ,BONNET WHEELHOUSE.		1,750.00	1,500.00
	DISCHARGE/CHARGE A/CON GAD AND RENEW CONDENSER.		240.00	240.00
	RENEW RADIATOR.		120.00	120.00
			6,076.00	4,436.00
	GRAND TOTAL		14,832.76	12,285.68

Report Ref No. CC3/QBE22000930/Eea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,500.00
---	--	--	-----------------

Report Ref No. CC3/QBE22000930/Eea3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SCN 8119E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SCN 8119E

RE-INSPECTION

