SM &UTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883 Email: SM AUTOMOTIVE@HOTMAIL.COM Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 24/01/2022

TPAXA

Estimated repair cost for vehicle no: SMC9994C RANGE ROVER EVOQUE 2.0 AT ABS 4WD HID SR

CHASSIS: SALVA2AG0CH620520 (2011)

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER FOIR	\$1,850.00	\$1,850.00
2	1	REAR BUMPER CENTER PAD Dela	\$780.00	\$780.00
3	2	REAR BUMPER SIDE PAD GARNISH	\$120.00	\$240.00
4	1	REAR BUMPER LOWER	\$345.00	\$345.00 \
5	1	REAR BUMPER REINFORCEMENT Devil &	\$780.00	\$780.00
6	2	REAR BUMPER BRACKET >4 ~	\$85.00	\$170.00 \(\psi \)
7	2	REAR BUMPER REFLECTOR ~~~	\$175.00	\$350.00 \(\tau \)
8	2	REAR BUMPER SIDE RETAINER ************************************	\$62.00	\$124.00
9	1	REAR END PANEL INNER 2 Pe 3	\$971.00	\$971.00 +
10	1	REAR END PANEL OUTER	\$684.00	\$684.00 +
11	1	REAR END PANEL TOP GARNISH N	\$286.00	\$286.00+
12	2	REAR BUMPER SENSOR Dand	\$185.00	\$370.00 /

TOTAL: **LESS 10 %**

SUB-TOTAL:

\$6,950.00 \$695.00 \$6,255.00

28/01/2022

S/N	Otv	ITEMS / SPECIAL NETT		U/price	Amount
1		REAR BUMPER CLIPS		\$80.00	\$80.00
2	1	REAR END PANEL SEALANT	2 2	\$120.00	\$120.00
3	1	REAR END PANEL TOP GARNISG CLIPS	In	\$60.00	\$60.00 -

30

TOTAL:

\$260.00 \$6,515.00

TOTAL PARTS:

Labour charges

LABOUR FOR PANEL BEATING

LABOUR FOR SPRAYPAINTING

3 WIRING CHECK

4 TO APPLY RUST PROOF / TUFF COAT ON ACCIDENT AREAS

TO RESET / TROUBLESHOOT & DIAGNOSE WARNING LIGHT ON

\$1,000.00 820

\$80.00 30

\$1,400.00

350

\$300.00 - 40

\$300.00 7

Subtotal :-

\$3,080.00

Total:-

\$9,595.00

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: