

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 201605878Z)
60 JALAN LAM HUAT, CARROS CENTRE
#05-68 (S737869)
Tel: 98888885

TO	: LONPAC	DATE	: 27-Jan-22
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
VEHICLE DETAILS			
		VEHICLE NO	: SJV9875Z
		MODEL	: MITSUBISHI LANCER

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID HINGES <i>bt</i>	2	\$ 185.00	\$ 370.00
2	BOOTLID KEY LOCK <i>bt</i>	1	\$ 225.00	\$ 225.00
3	BOOTLID LOGO <i>ne</i>	1	\$ 48.50	\$ 48.50
4	BOOTLID TOP LOCK <i>jam</i>	1	\$ 98.00	\$ 98.00
5	BOOT LID DETECTOR <i>ca</i>	1	\$ 298.00	\$ 298.00
6	BOOTLID WEATHERSTRIP <i>ne</i>	1	\$ 198.00	\$ 198.00
7	REAR BUMPER TOP BEAM <i>bt</i>	1	\$ 67.00	\$ 67.00
8	REAR BUMPER SIDE RETAINER <i>ne</i>	2	\$ 35.00	\$ 70.00
9	REAR BUMPER REINFORCEMENT <i>bt</i>	1	\$ 415.00	\$ 415.00
10	REAR BUMPER REFLECTOR <i>ca</i>	2	\$ 65.00	\$ 130.00
11	REAR REVERSE SENSOR WIRE HARNESS <i>at</i>	1	\$ 298.00	\$ 298.00
12	TAILAMP PANEL <i>bt</i>	2	\$ 298.00	\$ 596.00
13	TAILAMP WIRE HARNESS ?	1	\$ 382.00	\$ 382.00
14	REAR END PANEL <i>bt</i>	1	\$ 628.00	\$ 628.00
15	REAR END PANEL SIDE EXTENSION PANEL <i>bt</i>	2	\$ 241.00	\$ 482.00
16	REAR END PANEL TOP GARNISH ?	1	\$ 225.00	\$ 225.00
17	REAR FLOOR PANEL ?	1	\$ 895.60	\$ 895.60
18	REAR FLOOR PANEL TOP BOARD ?	1	\$ 289.20	\$ 289.20
19	REAR FLOOR SIDE PANEL EXTENSION ?	2	\$ 212.00	\$ 424.00
20	REAR FENDER <i>bt</i>	2	\$ 1,021.00	\$ 2,402.00
21	REAR FENDER INNER TRIM ?	2	\$ 334.00	\$ 668.00
22	REAR FENDER TOP TRIM ?	2	\$ 211.00	\$ 422.00

23	REAR FENDER WHEEL HOUSING ?	2	\$ 587.00	\$ 1,174.00
24	REAR DOOR INNER LOCK X	2	\$ 251.00	\$ 502.00
25	REAR DOOR WEATHERSTRIPE X	2	\$ 159.00	\$ 318.00
26	REAR PASSENGER SEAT TOP BOARD ?	1	\$ 459.00	\$ 459.00
27	REAR PASSENGER SEAT SET X	1	\$ 2,500.00	\$ 2,500.00
28	REAR WINDSCREEN GLASS bro /	1	\$ 1,259.00	\$ 1,259.00
29	REAR WINDSCREEN GLASS MOULDING an /	1	\$ 198.00	\$ 198.00
30	REAR CHASSIS EXTENSION repair	2	\$ 312.00	\$ 624.00
31	REAR CROSSMEMBER repair	1	\$ 1,985.00	\$ 1,985.00
32	REAR SPARE TYRE BOLT X	1	\$ 68.00	\$ 68.00
33	REAR EXHAUST MOUNTING ?	2	\$ 18.00	\$ 36.00
34	REAR EXHAUST INSULATOR H /	1	\$ 221.00	\$ 221.00

TOTAL PRICE	\$ 18,975.30
LESS 10%	\$ 1,897.53
SUB TOTAL PRICE	\$ 17,077.77

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	BOOTLID FIBRE ca /	1	\$ 2,500.00	\$ 2,500.00
2	BOOTLID INSULATOR CLIPS re /	8	\$ 6.50	\$ 52.00 30
3	BOOTLID LAMP ca /	2	\$ 350.00	\$ 700.00
4	BOOTLID THIRD BRAKE LIGHT ?	1	\$ 300.00	\$ 300.00
5	BOOTLID ABSORBER ?	2	\$ 300.00	\$ 600.00
6	TAILAMP ca /	2	\$ 500.00	\$ 1,000.00
7	REAR NUMBER PLATE ca /	1	\$ 50.00	\$ 50.00 35
8	REAR BUMPER FIBRE ca /	1	\$ 2,000.00	\$ 2,000.00
9	REAR BUMPER CLIPS re /	10	\$ 6.50	\$ 65.00
10	REAR END PANEL TOP GARNISH CLIPS re /	2	\$ 6.50	\$ 13.00
11	REAR FENDER INNER TRIM CLIPS re /	12	\$ 6.50	\$ 78.00 40
12	REAR WINDSCREEN GLASS SEALANT re /	1	\$ 80.00	\$ 80.00 60
13	REAR WINDSCREEN GLASS INNER SEAL re /	1	\$ 50.00	\$ 50.00 30
14	REAR WINDSCREEN TINTED re /	1	\$ 200.00	\$ 200.00
15	REAR FLOOR PANEL INSULATION SEAL ?	1	\$ 150.00	\$ 150.00
16	REAR END PANEL INSULATION SEAL ?	1	\$ 100.00	\$ 100.00
17	REAR EXHAUST PIPE AFTER MARKET ?	1	\$ 3,000.00	\$ 3,000.00
18	REAR SHOCKABSORBER AFTER MARKET X	2	\$ 300.00	\$ 600.00
19	SPARE TYRE C/W RIM X	1	\$ 300.00	\$ 300.00
20	TOOLS SET X	1	\$ 100.00	\$ 100.00
21	REAR CAMERA ca / X	1	\$ 350.00	\$ 350.00 250X
22	REVERSE CAMERA ca /	1	\$ 350.00	\$ 350.00 250

23	REVERSE SENSOR <i>new</i>	1	\$ 280.00	\$ 280.00 <i>200</i>
----	---------------------------	---	-----------	---------------------------------

TOTAL \$ 12,918.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR PORTION)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 3,200.00	<i>2000</i>	
2	TO SPRAY PAINT	\$ 2,600.00	<i>1400</i>	
3	TO SPRAY TUFF COAT	\$ 200.00	<i>100/20</i>	
4	WIRING, BULB CHECKING	\$ 80.00	<i>30</i>	
5	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 350.00	<i>120</i>	
6	REMOVE AND REFIX REAR EXHAUST	\$ 150.00	<i>80</i>	
7	REMOVE AND REFIX REAR FUEL TANK TO FACILITATE REPAIR	\$ 200.00	<i>80</i>	
8	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$ 150.00	<i>120</i>	
9	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 400.00	<i>180?</i>	
10	CONDUCT WHEEL ALIGNMENT	\$ 120.00	<i>60</i>	
11	CONDUCT WATER LEAKAGE TEST	\$ 150.00	<i>X</i>	
12	REMOVE AND REFIX REVERSE SENSOR	\$ 100.00	<i>60</i>	
13	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>100</i>	

TOTAL \$ 7,950.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 29,995.77
TOTAL LABOUR COST : \$ 7,950.00
TOTAL REPAIR COST : \$ 37,945.77

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

14 days

45

26/01/22 @1610

Reg after repair

Repair / not check

Required to check parts price