



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-9500111-X

ESTIMATE FOR XE6043B

SembWaste Pte Ltd

30 Hill Street
#05-04
Singapore 179360

67233200A/C

17 May
918 4593

Vehicle & Document Information

WIP No 53802
Reg No/Reg Date XE6043B / 27/11/2020
Date In/Mileage XE6043B
Chassis No W1T98401420463978X
Engine No 936912C0211236
Make/Model MBCV/Arocs 2630 6X4 3
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
WS000458	Credit	10/01/2022/ 17:31		610 / Philip Cheong
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

A 00940101	TO REMOVE & REFIT FRONT FENDER, FRONT STEP, PANEL & FRONT BUMPER	1.00	260.05	30.00	1872.00
	TO PUTTY & SPRAY PAINTING	1.00	94.84	30.00	602.03
M	STEP PLATE / BR (arch lane)	1.00	48.09	30.00	66.39
M	COVER / mis (m. m.)	1.00	109.11	30.00	33.66
M	COVER / mis (m. m.)	1.00	547.46	30.00	76.38
M	ADD. TURN SIGNAL LAMP / BR	1.00	230.89	30.00	383.22
M	FRONT FOG LAMP	1.00	733.11	30.00	161.62
M	COVER FRAME X	1.00	320.33	30.00	513.18
M	BUMPER, FRONT X	1.00	49.92	30.00	224.23
M	FRONT SPOILER X BR (h. m.)	1.00	740.05	30.00	34.94
M	FACING X	1.00	1143.84	30.00	518.03
M	ENTRANCE / BR (arch upper)	1.00			800.69
M	LAMP UNIT X				

ESTIMATE
NOT AN OFFICIAL TAX INVOICE
Steve (LKK)
27/11/22, 19.00a
M L
PIP
by Bel
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To rectify before/after spray painting
- To display damaged part(s) during rectify
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Confirmed & accepted by [Signature] must be rectified and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorized signatory and company stamp

Nett 5,286.37
7% GST on 5286.37 370.05
Total Payable 5,656.42

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Gardens MBCV Customer Service Center
209 Pandan Gardens
Singapore 609339
Tel: (65) 67714369
Fax: (65) 67756310
www.mercedes-benz.com.sg