

HUI HUANG HONG BAO MOTORS

2 Kaki Bukit Ave 2 #02-11 Kaki Bukit AutoHub Singapore 417921

Tel : 6844 7414 Fax : 6844 7401 Email : alisonhbb@gmail.com

M/s Popular Rent A Car Pte Ltd
501 Guillemard Road
Singapore 399840

20th January 2022

Date of survey: 26 January 2022

Motor surveyor: LKK Consultants Pte Ltd

Surveyor: Thevan

Type of repair: Lump Sum

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate cost of repairs to Hyundai Sonata - SLH 4878 Z

1 pc	Rear bumper	\$ 588.00	PT
1 pc	Rear bumper lower cover	\$ 144.00	cut
1 pc	Rear bumper under center cover	\$ 30.00	cut
1 pc	Rear bumper reflector RH	\$ 32.00	cr
1 pc	Rear bumper reinforcement	\$ 435.30	PT
1 pc	Rear bumper reinforcement beam RH	\$ 142.70	PT
1 pc	Rear bumper retainer RH	\$ 39.20	nec
1 pc	Rear end panel	\$ 417.70	cr
1 pc	Rear end panel garnish	\$ 64.00	cut
1 pc	Boot lid	\$ 1,490.00	cr
1 pc	Boot lid reflector RH	\$ 868.00	scr
1 pc	Boot lid 'H' emblem	\$ 27.50	nec
1 pc	Boot lid 'SONATA' emblem	\$ 42.20	nec
1 pc	Boot lid hinge RH	\$ 152.80	scr
1 pc	Boot lid rubber	\$ 99.50	scr
1 pc	Boot lid lock	\$ 112.00	scr jam
1 pc	Boot lid striker	\$ 22.00	PT
1 pc	Boot floor panel cover	\$ 216.20	scr
1 pc	Taillamp RH	\$ 794.20	scr
		\$ 5,717.30	
	Less 20%	\$ 1,143.46	
		\$ 4,573.84	2672.88

1 set	Reverse sensors	cut	\$ 250.00	SN 200
1 set	Rear bumper clips	nec	\$ 30.00	SN 70
1 set	Boot lid inner clips	nec	\$ 30.00	SN 70

Labour charges to panel beating, remove, renew and align replaced parts etc

\$ 800.00 600

To jack and repair rear exhaust tail pipe

\$ 100.00 50

To remove and refit back-up camera

\$ 60.00 20

To remove and refit reverse sensors

\$ 60.00 20

Spray painting

\$ 1,000.00 800

Wiring charges

\$ 50.00 10

Tuff-kote

\$ 50.00 20

\$ 7,003.84

Dollars : Seven thousand three dollars and eighty-four cents

3550

RD: 5