



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:STACEY		Ref: CC4/ASM22000946/Bpa3q2 Date: 19/07/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 8800K	Veh. Inspected	YP 7646K
Policy No.	P2441305	Coverage (\$)	0.00
Claim No.	S2M03RAX	Excess (\$)	0.00
Assign From		Assign Date	27/01/2022
2. Vehicle Particulars & Condition			
Make & Model	ISUZU NPR85UH5A	c.c	2999
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JAANPR85HH7100977	Colour	WHITE
Odometer	41948 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/16	YOKOHAMA	4 mm
L/H Front Tyre	195/16	YOKOHAMA	4 mm
R/H Rear Tyre	205/16	GRENLANDER	4 mm
L/H Rear Tyre	205/16	GRENLANDER	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/01/2022	Inspection Date	17/02/2022
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	