



19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SLC9798P	MODEL : FORESTER 2.0XT AWD CVT
REF NO:	YEAR: 31-MAY-2016
ENGINE NO: FA20A930996	CHASSIS NO: JF1SJGK85GG072238
DOA: 17/01/2022	TOA: 1700 HRS
TYPE OF CLAIM: 3RD PARTY	INS COMPANY: CHINA TAIPING

S/N	NATURE OF JOB	AMOUNT
1.	TO REMOVE AND REPLACE FRONT BUMPER,ENERGY ABSORBER,LHS FOG LAMP COVER	\$1740.00
2.	TO RESPRAY FRONT BUMPER, ENERGY ABSORBER AND LHS FENDER	\$1440.00
3.	TO CONDUCT FRONT LIGHTING TEST	\$150.00
4.	SUNDRIES	\$100.00
5.		
6.		
7.		
8.		
9.		
10.		
	Total Labour	\$3430.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	
HP / EMAIL:	/
BEFORE PAINT:	
DAYS GIVEN:	

Estimate

Date 01 / 24 / 2022

001 / 001

Name	SLC9798P	Tel (Home)	
Address		Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Body Model	SJGDKK8
		Vin-Code	JF1SJGK85GG072238

Part Number	Part Code Name	Part Code	Q'ty	Price
84002SG232	LAMP ASSEMBLY-HEAD LEFT	FIG-840 84001B	1	2,380.00
86636SG350TQ	COVER ASSEMBLY-LAMP WASHER NOZ ZLE, LEFT	FIG-877 866360A	1	55.50
86636SG371	NOZZLE-LAMP WASHER, LEFT	FIG-877 866360	1	81.40
57709SG011	BUMPER FACE-FRONT	FIG-590 57704	1	610.50
57731SG130	COVER-FRONT BUMPER, LEFT	FIG-590 57731B	1	13.00
57731SG090	COVER-FOG LIGHT, LEFT	FIG-590 849530	1	44.40
57707SG030	BRACKET-FRONT BUMPER SIDE, LEFT	FIG-590 57707G	1	13.00
57707SG010	BRACKET-FRONT BUMPER CORNER, LE FT	FIG-590 57707AG	1	37.00
57722SG020	ENERGY ABSORBER-FRONT BUMPER	FIG-590 57705	1	129.50
57120SG0309P	Fender Front Left	Page-Total	1	277.50
		Sub-Total		
		Total		3,364.30
		Tax		0.00
		Grand Total		3,364.30

Memo

Grand Total
3641.80

--

Tel
