

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jan 2022 Sendback Est	26 Jan 2022 17:32 S\$ 12,897.45	27 Jan 2022 10:36 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	HUSSEIN BIN KAMARUDIN , ID : S7515734G		
Vehicle Reg. No.:	SJZ7606B	Date of Loss :	22/09/2021 14:00 - :59 [8 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM21D206219/C01/TANCHC	Policy/Cover Note No. :	DMPCSNW00062352100 (Comprehensive)
		Excess:	S\$3,500.00
Repairer:	Goldbell Engineering Pte Ltd (Tuas) 10 Tuas Ave 18, 638894 Tuas - Tel: 6864 0695 / 6864 0698		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jacqueline Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 09/02/2022]		
Driver/Custodian:	HUSSAINI HAZIQ BIN HUSSEIN (/ Male) , NRIC: T0220010J Email:		
Adj Asg. Remarks:	Insured driver mentioned the steering wheel got mechanical issue and cause the accident. Please update us after survey.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

ALL ASSOCIATED FILE NOTES

[Create New](#)

No.	Status	Type	Viewer/ Assigned To	Note	Created On	Created By	1st Read By
No results.							

