

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jacqueline Tan

Date: 28 Jan 2022

## **Preliminary Advice**

|                    |                                                                             |                         |                      |
|--------------------|-----------------------------------------------------------------------------|-------------------------|----------------------|
| Vehicle No         | : SJZ7606B                                                                  | Accident Date           | : 22/09/2021         |
| Make               | : HYUNDAI AVANTE                                                            | Policy No.              | : DMPCSNW00062352100 |
| Assignment Date    | : 27/01/2022                                                                | Excess                  | : S\$3,500.00        |
| Date of Inspection | : 27/01/2022                                                                | Est. Duration of Repair | : 14                 |
| Inspection At      | : GOLDBELL ENGINEERING PTE LTD (TUAS)<br>10 TUAS AVE 18<br>SINGAPORE 638894 |                         |                      |

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 12,897.45 |
| Revised Amount              | :S\$ | 8,392.45  |
| Check Items (Estimated)     | :S\$ | 2,891.00  |
| Total                       | :S\$ | 11,283.45 |

Lump Sum Repair :S\$

## **Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 28,000.00 |
| COE / PARF Rebate  | :S\$ | 14,632.00 |

|                   |      |           |
|-------------------|------|-----------|
| Salvage Value     | :S\$ |           |
| Margin for Repair | :S\$ | 13,368.00 |

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Due to external damages, our surveyor unable to test steering condition.  
The vehicle repair on Lump Sum Basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.