



CROWN ASIA BUS BUILDER PTE LTD

44 SUNGAI KADUT AVE, SINGAPORE 729667

Tel : +65 6467 0956 Fax : +65 6469 4319

Email : crownasia@hotmail.sg

Company Reg No: 201023449R

6/11/2017 /

First Capital Insurance Ltd
c/o : Surveyor

Dear Sirs ,

THIRD PARTY CLAIM – REPAIR ESTIMATE FOR PA 9349 R

Traffic accident on 21/2/2017 involving PA 9349 R , YP 6451 L AND SHD 4640 K ALONG JURONG EAST AVENUE 1. .

We append below the repair estimate for PA 9349 R (Isuzu LT 134P))

Parts required :-

1 pc	Rear bumper repair	\$ 3800.00 x	3250
1 pc	Rear right inspection lid cover dented	\$ 4200.00 3250	10%
2 pcs	Rear right inspection lid cover lock xnn	\$ 180.00 x	2925
1 pc	Rear right top body panel repair	\$ 4200.00 x	
		\$12380.00	
	Less 10% trade discount	\$ 1238.00	
		\$11142.00	
1 pc	Rear right window glass gum xnn	\$ 200.00 x	
	Total parts cost	\$11342.00	

Labour charges :-

To remove rear right window glass so as to enable repair to be carried out and refit same. \$ 300.00 **xnn**

To remove rear right seats, inner trim board etc. so as to enable To be carried out and refit same. \$ 300.00 **100**

To putty and spray painting on rear bumper , rear right body panel, Rear right inspection lid cover and all affected accident parts. \$ 1800.00 **900**

b.c.f. \$13742.00 **1000**

...2/-

CROWN ASIA BUS BUILDER PTE LTD

PA 9349 R

b.b.f. \$13742.00


To straighten rear right body structural frame assy. To knock/
Straighten all necessary parts including repairing and changing
Of all damaged parts and align same.

\$ 1500.00 **750**

Total repair cost \$15242.00

Note :- This estimate is based on visible damage only. Should any hidden parts and/or labour charges required during works in progress , insurer and/or their surveyor will be notified accordingly.

CROWN ASIA BUS BUILDER PTE LTD



David Liang (H/P 96662662)
Claims Consultant

2925

1000

750

4675

20%

3740

L/S-\$3,750/5DAYS