

TEAM MOTION

ESTIMATE

Our Ref: C2022002/TP/25.1.22

Vehicle number: SMW2966A

Vehicle Made & Model: Audi A8L 3.0 TFSI Quattro

Items	Qty	List Items
1	1	LH side mirror housing
2	1	LH side mirror top cover
3	1	Mirror <i>glass</i>
4	1	Turn Signal
5	1	LH Wing Mirror Camera

	Amount \$
<i>1600.32</i>	<i>CNE</i> 2,311.20
<i>165.00</i>	<i>CNE</i> 222.56
	<i>17</i> 821.76 <i>X</i>
	<i>CNE</i> 139.96
	<i>17</i> 644.14 <i>X</i>
Sub-total	4,139.62
Less 10%	
Total List	

Labour charges

- | | | |
|---|--|--------|
| 6 | To check rear electrical wiring | 80.00 |
| 7 | To remove, replace & refix parts and mirror camera | 400.00 |
| 8 | To respray painting and etc | 400.00 |

Total Labour 880.00 *200*

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

*Not Authorized
28/1/22
2/3 \$1650/
2 days.
Submit to insurance*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*9-1905.28
102
9-1714.75
2-350
2064.75
222
1681.*