

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLD8930A

Vehicle Model : MAZDA 2

Chassis Number : MM6DL2SAAGW185601

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BOOT LID	1	\$ 861.80
2	BOOT LID LOCK	1	\$ 190.90
3	BOOT LID HINGES (LH & RH)	2	\$ 247.80
4	BOOT LID INNER TRIM	1	\$ 302.60
5	BOOT LID INNER TRIM CLIPS	15	\$ 75.00
6	BOOT LID WEATHERSTRIP	1	\$ 112.90
7	BOOT LID LOGO	1	\$ 58.20
8	"MAZDA 2" EMBLEM	1	\$ 60.00
9	"SKYACTIV" EMBLEM	1	\$ 67.60
10	BOOT LID LAMP (LH & RH)	2	\$ 416.40
11	REAR BUMPER	1	\$ 954.50
12	REAR BUMPER CLIPS	10	\$ 50.00
13	REAR BUMPER RETAINER (LH & RH)	2	\$ 50.00
14	REAR BUMPER REFLECTOR (LH & RH)	2	\$ 106.00
15	REAR BUMPER LOWER LIP	1	\$ 850.00
16	REAR FENDER (LH & RH)	2	\$ 1983.20
17	TAIL LAMP (LH & RH)	2	\$ 790.60
18	TAIL LAMP PANEL (LH)	1	\$ 575.40
19	REAR SPLASH SHIELD (LH& RH)	2	\$ 140.00
20	REAR SPLASH SHIELD CLIPS	30	\$ 150.00
21	END PANEL	1	\$ 656.00
22	END PANEL UPPER GARNISH	1	\$ 80.00
23	END PANEL UPPER GARNISH CLIPS	10	\$ 50.00
24	SPARE TYRE TANK	1	\$ 1102.50
25	SPARE TYRE TANK UPPER BOARD	1	\$ 292.30
26	REAR LHS FENDER INNER TRIM	1	\$ 182.50
27	REAR LHS FENDER INNER TRIM CLIPS	10	\$ 50.00
28	REAR WINDSCREEN	1	\$ 922.80
29	REAR WINDSCREEN INNER SEAL	1SET	\$ 120.00

Discount Less	20%	\$	11499.00
List Prices Total		\$	2299.80
		\$	9,199.20

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

S/N	Special Nett Items:	Qty		
1	REAR NUMBER PLATE WITH HOLDER	1SET	\$	60.00
2	REVERSE SENSORS	1SET	\$	450.00
3	REAR WINDSCREEN SEALANT	1	\$	50.00
Special Nett Total			\$	560.00
Spare Part's Total Price			\$	9759.20

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLD8930A

Vehicle Model : MAZDA 2

Chassis Number : MM6DL2SAAGW185601

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$ 2000.00
2	TO SPRAY PAINTING ON: BOOT LID, REAR BUMPER, REAR END PANEL, REAR BOTH FENDER, SPARE TYRE TANK, END PANEL.	\$ 1800.00
3	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION.	\$ 200.00
4	REMOVE & INSTALL REAR WINDSCREEN .	\$ 200.00
5	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	\$ 150.00
6	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO BOOT LID & TEST FUNCTION	\$ 200.00
7	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$ 280.00
Labour Total		\$ 4830.00
Parts & Labour Total		\$ 14589.20