

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLD8930A

Vehicle Model : MAZDA 2

Chassis Number : MM6DL2SAAGW185601

Estimated Repair Cost

9 days

S/N	Parts Description	Qty	List Price
1	BOOT LID	1	\$ 861.80
2	BOOT LID LOCK	1	\$ 190.90
3	BOOT LID HINGES (LH & RH) o/s di	2	\$ 247.80
4	BOOT LID INNER TRIM	1	\$ 302.60
5	BOOT LID INNER TRIM CLIPS	15	\$ 75.00
6	BOOT LID WEATHERSTRIP	1	\$ 112.90
7	BOOT LID LOGO	1	\$ 58.20
8	"MAZDA 2" EMBLEM	1	\$ 60.00
9	"SKYACTIV" EMBLEM	1	\$ 67.60
10	BOOT LID LAMP (LH & RH) NIS CM o/s Bu	2	\$ 416.40
11	REAR BUMPER 896.	1	\$ 954.50
12	REAR BUMPER CLIPS	10	\$ 50.00
13	REAR BUMPER RETAINER (LH & RH) NIS di	2	\$ 50.00
14	REAR BUMPER REFLECTOR (LH & RH) NIS CM	2	\$ 106.00
15	REAR BUMPER LOWER LIP	1	\$ 850.00
16	REAR FENDER (LH & RH) @ 948.00 NIS Bu	2	\$ 1983.20
17	TAIL LAMP (LH & RH)	2	\$ 790.60
18	TAIL LAMP PANEL (LH) 396.00 NIS CM	1	\$ 575.40
19	REAR SPLASH SHIELD (LH & RH)	2	\$ 140.00
20	REAR SPLASH SHIELD CLIPS	30	\$ 150.00
21	END PANEL 656	1	\$ 656.00
22	END PANEL UPPER GARNISH	1	\$ 80.00
23	END PANEL UPPER GARNISH CLIPS	10	\$ 50.00
24	SPARE TYRE TANK	1	\$ 1102.50
25	SPARE TYRE TANK UPPER BOARD	1	\$ 292.30
26	REAR LHS FENDER INNER TRIM	1	\$ 182.50
27	REAR LHS FENDER INNER TRIM CLIPS	10	\$ 50.00
28	REAR WINDSCREEN	1	\$ 922.80
29	REAR WINDSCREEN INNER SEAL	1	\$ 120.00
	1 SET		\$ 120.00

Discount Less 20% \$ 11499.00
List Prices Total \$ 2299.80
\$ 9,199.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

SN	Special Nett Items:	Qty	
1	REAR NUMBER PLATE WITH HOLDER	1SET	\$ 60.00 X svc
2	REVERSE SENSORS	1SET	\$ 450.00 <i>2005mm</i>
3	REAR WINDSCREEN SEALANT	1	\$ <i>50.00 405ml</i>
Special Nett Total			\$ 560.00
Spare Part's Total Price			\$ 9759.20

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLD8930A

Vehicle Model : MAZDA 2

Chassis Number : MM6DL2SAAGW185601

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$ 2000.00 <i>1200</i>
2	TO SPRAY PAINTING ON: BOOT LID, REAR BUMPER, REAR END PANEL, REAR BOTH FENDER, SPARE TYRE TANK, END PANEL.	\$ 1800.00 <i>1250</i>
3	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION.	\$ 200.00 <i>50</i>
4	REMOVE & INSTALL REAR WINDSCREEN.	\$ 200.00 <i>120</i>
5	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	\$ 150.00 <i>20</i>
6	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO BOOT LID & TEST FUNCTION	\$ 200.00 <i>50</i>
7	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$ 280.00 <i>280.00</i> <i>X</i>

Labour Total \$ 4830.00

Parts & Labour Total \$ 14589.20