

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLD8930A

Vehicle Model : MAZDA 2

Chassis Number : MM6DL2SAAGW185601

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BOOT LID	1	\$ 861.80 bent
2	BOOT LID LOCK	1	\$ 190.90 Repair
3	BOOT LID HINGES (LH & RH)	2	\$ 247.80 n/s bent
4	BOOT LID INNER TRIM	1	\$ 302.60 deformed
5	BOOT LID INNER TRIM CLIPS	15	\$ 75.00 nec
6	BOOT LID WEATHERSTRIP	1	\$ 112.90 dist/dented 50% sn
7	BOOT LID LOGO	1	\$ 58.20 nec
8	"MAZDA 2" EMBLEM	1	\$ 60.00 nec
9	"SKYACTIV" EMBLEM	1	\$ 67.60 nec
10	BOOT LID LAMP (LH & RH)	2	\$ 416.40 n/s cracked o/s ?
11	REAR BUMPER	1	\$ 954.50 bent
12	REAR BUMPER CLIPS	10	\$ 50.00 nec
13	REAR BUMPER RETAINER (LH & RH)	2	\$ 50.00 n/s cracked
14	REAR BUMPER REFLECTOR (LH & RH)	2	\$ 106.00 n/s broken
15	REAR BUMPER LOWER LIP	1	\$ 850.00 cracked
16	REAR FENDER (LH & RH)	2	\$ 1983.20 n/s buckled
17	TAIL LAMP (LH & RH)	2	\$ 790.60 n/s cracked
18	TAIL LAMP PANEL (LH)	1	\$ 575.40 bent
19	REAR SPLASH SHIELD (LH& RH)	2	\$ 140.00 ?
20	REAR SPLASH SHIELD CLIPS	30	\$ 150.00 ?
21	END PANEL	1	\$ 656.00 bent
22	END PANEL UPPER GARNISH	1	\$ 80.00 buckled
23	END PANEL UPPER GARNISH CLIPS	10	\$ 50.00 nec
24	SPARE TYRE TANK	1	\$ 1102.50 repair
25	SPARE TYRE TANK UPPER BOARD	1	\$ 292.30 ?
26	REAR LHS FENDER INNER TRIM	1	\$ 182.50 ?
27	REAR LHS FENDER INNER TRIM CLIPS	10	\$ 50.00 ?
28	REAR WINDSCREEN	1	\$ 922.80 cut
29	REAR WINDSCREEN INNER SEAL	1SET	\$ 120.00 nec

Discount Less	20%	\$	11499.00
List Prices Total		\$	2299.80
		\$	9,199.20

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

S/N	Special Nett Items:	Qty			
1	REAR NUMBER PLATE WITH HOLDER	1SET	\$	60.00	dented
2	REVERSE SENSORS	1SET	\$	450.00	dented
3	REAR WINDSCREEN SEALANT	1	\$	50.00	nec
Special Nett Total			\$	560.00	
Spare Part's Total Price			\$	9759.20	

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLD8930A

Vehicle Model : MAZDA 2

Chassis Number : MM6DL2SAAGW185601

S/N	Labour Descriptions	Charges	
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$	2000.00 1200
2	TO SPRAY PAINTING ON: BOOT LID, REAR BUMPER, REAR END PANEL, REAR BOTH FENDER, SPARE TYRE TANK, END PANEL.	\$	1800.00 1100
3	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION.	\$	200.00 50
4	REMOVE & INSTALL REAR WINDSCREEN .	\$	200.00 120
5	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	\$	150.00 20
6	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO BOOT LID & TEST FUNCTION	\$	200.00 50
7	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$	280.00 ?
Labour Total		\$	4830.00
Parts & Labour Total		\$	14589.20