

ASS. REC. BY:

REF:

Smo / 22 000 966 / Kv

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



# ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLD8930A

Vehicle Model : MAZDA 2

Chassis Number : MM6DL2SAAGW185601

Estimated Repair Cost

*Not Authorized  
L1 Sy @  
Resurvey After Repair*

*Keneth CLK/c  
98910663*

S/N	Parts Description	Qty	List Price
✓ R 1	BOOT LID	1	\$
R X 2	BOOT LID LOCK	1	\$
N/S R 3	BOOT LID HINGES (LH & RH)	2	\$
Defm ✓ 4	BOOT LID INNER TRIM	1	\$
Ne ✓ 5	BOOT LID INNER TRIM CLIPS	15	\$
Dis/R 6	BOOT LID WEATHERSTRIP	1	\$ 508.00
Ne ✓ 7	BOOT LID LOGO	1	\$
Ne ✓ 8	"MAZDA 2" EMBLEM	1	\$
Ne ✓ 9	"SKYACTIV" EMBLEM	1	\$
N/S CM 10	BOOT LID LAMP (LH & RH)	2	\$ 0.15?
R ✓ 11	REAR BUMPER	1	\$
Ne ✓ 12	REAR BUMPER CLIPS	10	\$
N/S CM 13	REAR BUMPER RETAINER ( LH & RH)	2	\$ 4
N/S R 14	REAR BUMPER REFLECTOR (LH & RH)	2	\$ 4
? 15	REAR BUMPER REINFORCEMENT	1	\$
? 16	REAR BUMPER REINFORCEMENT BRACKET (LH & RH)	2	\$
CM ✓ 17	REAR BUMPER LOWER LIP	1	\$
N/S R 18	REAR FENDER (LH & RH)	2	\$ 4
N/S CM 19	TAIL LAMP (LH & RH)	2	\$ 4
R ✓ 20	TAIL LAMP PANEL (LH)	1	\$
? 21	REAR SPLASH SHIELD (LH & RH)	2	\$
? 22	REAR SPLASH SHIELD CLIPS	30	\$
R ✓ 23	END PANEL	1	\$
R ✓ 24	END PANEL UPPER GARNISH	1	\$
Ne ✓ 25	END PANEL UPPER GARNISH CLIPS	10	\$
R X 26	SPARE TYRE TANK	1	\$
? 27	SPARE TYRE TANK UPPER BOARD	1	\$
? 28	REAR LHS FENDER INNER TRIM	1	\$
? 29	REAR LHS FENDER INNER TRIM CLIPS	10	\$
W ✓ 30	REAR WINDSCREEN	1	\$
Ne ✓ 31	REAR WINDSCREEN INNER SEAL	1 SET	\$

**LKK Auto Consultants** hence notify

the Repairer of the following:

• To resurvey before/after spray painting.

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey on a "Without Prejudice" basis

• No illegal modifications is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Discount Less 20%

List Prices Total

Acknowledged by Repairer

Signature:

Date:

# ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

S/N	Special Nett Items:	Qty	
<i>Pat ✓</i> 1	REAR NUMBER PLATE WITH HOLDER	1SET	\$
<i>Pat ✓</i> 2	REVERSE SENSORS	1SET	\$
<i>Man</i> 3	REAR WINDSCREEN SEALANT	1	\$
Special Nett Total			\$
Spare Part's Total Price			\$

**ELITE AM PTE LTD**  
280 Woodlands Industrial Park E5, #01-17,  
Harvest @ Woodlands Singapore 757322  
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLD8930A

Vehicle Model : MAZDA 2

Chassis Number : MM6DL2SAAGW185601

S/N	Labour Descriptions	Charges	
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$	2000.00 1200
2	TO SPRAY PAINTING ON: BOOT LID, REAR BUMPER, REAR END PANEL, REAR BOTH FENDER, SPARE TYRE TANK, END PANEL.	\$	1800.00 1100
3	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION.	\$	200.00 50
4	REMOVE & INSTALL REAR WINDSCREEN .	\$	200.00 120
5	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	\$	150.00 20
6	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO BOOT LID & TEST FUNCTION	\$	200.00 50
7	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$	280.00 7

Labour Total \$ 4830.00

Parts & Labour Total \$



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission 27/01/2022 10:35 (SGT)  
Date of Accident 26/01/2022 13:00 (SGT)  
Exact Location of Accident Singapore  
Additional Location Information Bedok Road turning right into Shell petrol station  
Country/State of Loss Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SLD8930A  
INSURED/POLICYHOLDER  
Is company? No  
Name Of Registered Owner Wong Liang Yen  
NRIC No SXXXX114Z  
Email Address kylin.hongyu@gmail.com  
Mobile Phone No (Phone) +65-93551266  
Alternative Phone No +65-93551266

## VEHICLE PARTICULARS

Manufacturer Mazda  
Model 2  
Variant -  
Exact purpose for which vehicle was being used at time of accident Private use  
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party  
Vehicle Category Private car  
Transmission Auto  
CC 1496


## INSURANCE COMPANY

Name of Insurance Company AXA Insurance Pte Ltd  
Type of Coverage Comprehensive  
Fleet Policy No  
Policy Number GA208002/1  
Cover Note Number -

## DRIVER

Name of Driver Wong Hong Yu  
NRIC No SXXXX003H

# SKETCH PLAN



A : SLDB930A

B : GBJ 6190T

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26 January at about 1300HRS, I was driving along Bedok Road. I signalled right to turn into shell petrol station and slowed down gradually to a stop to allow oncoming traffic to pass. Suddenly, vehicle B hit me in the rear.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: