

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 18 Mar 2022

Preliminary Advice

Insured : GBH4977P
Vehicle No
TP Vehicle No : SKQ6865L
Make : KIA FORTE K3
Date of Inspection : 14/03/2022
Inspection At : CHENG HOE MOTOR PTE LTD (AMK)
10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO
AUTOPOINT
SINGAPORE 568047

Accident Date : 26/01/2022
Assignment Date : 27/01/2022
Est. Duration of Repair : 5

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,449.04
Revised Amount	:S\$	3,805.94
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,805.94

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.