

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST: 201001158E RCB NO: 201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)  
 16 RAFFLES QUAY  
 #24-01 HONG LEONG BUILDING  
 SINGAPORE 048581  
 TEL: 68277660 FAX: 62257402  
 ATTN: Motor Claim Department  
 WS Ref: TP/MSIG/AMK  
 Claim Type: Third Party  
 Accident Date: 26/01/2022  
 TP Veh Reg No: GBH4977P

*Not Withheld*  
*11 Pp 23000h*  
*Pruning After Paint 4 days*  
 Estimate No: ES2290213/AMK  
 Date: 14 Mar 2022  
 Policy No: 5069104575-07 DC  
 Veh Reg No: SKQ6865L  
 Make/Model: KIA FORTE K3 1.6A  
 Chassis No: KNAFZ411MF5349152  
 Engine No: G4FGEH748600  
 Reg. Date: 19/12/2014

## Estimate Repair Cost to Vehicle No :SKQ6865L

| Description                                                                                                                                             | U/Price  | Quantity | List Price<br>S\$ | Amount<br>S\$ |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------|-------------------|---------------|
| <b>List Price</b>                                                                                                                                       |          |          |                   |               |
| 1 FRONT BUMPER CLIP                                                                                                                                     | 4.80     | 6 PC     | 28.80             | ✓             |
| 2 FRONT LH FENDER                                                                                                                                       | 377.00   | 1 PC     | 377.00            | ✓             |
| 3 FRONT LH FENDER INNER SHIELD                                                                                                                          | 81.00    | 1 PC     | 81.00             | ✓             |
| 4 FRONT LH FENDER INNER SHIELD CLIP                                                                                                                     | 4.80     | 6 PC     | 28.80             | ✓             |
| 5 HEADLAMP LH <i>1355</i>                                                                                                                               | 1,795.00 | 1 PC     | 1,795.00          | X             |
| 6 FRONT LH DOOR                                                                                                                                         | 1,355.00 | 1 PC     | 1,355.00          | ✓             |
| 7 FRONT LH DOOR FRAME STICKER                                                                                                                           | 46.00    | 1 PC     | 46.00             | ✓             |
| 8 FRONT LH DOOR TOP HINGE                                                                                                                               | 33.00    | 1 PC     | 33.00             | X             |
| 9 FRONT LH DOOR CHECKER                                                                                                                                 | 46.00    | 1 PC     | 46.00             | X             |
| 10 FRONT LH DOOR BOTTOM HINGE                                                                                                                           | 34.00    | 1 PC     | 34.00             | X             |
| 11 FRONT LH RIM <i>790</i>                                                                                                                              | 790.00   | 1 PC     | 790.00            | ✓             |
| 12 FRONT LH KNUCKLE ARM                                                                                                                                 | 420.00   | 1 PC     | 420.00            | X             |
| 13 FRONT LH WHEEL BEARING                                                                                                                               | 131.00   | 1 PC     | 131.00            | X             |
|                                                                                                                                                         |          |          | 5,165.60          |               |
|                                                                                                                                                         | Less 10% |          | 516.56            | 4,649.04      |
| <b>Special Net</b>                                                                                                                                      |          |          |                   |               |
| 14 DOOR VISOR                                                                                                                                           | 150.00   | 1 SET    | 150.00            | ✓             |
|                                                                                                                                                         |          |          | 150.00            | 150.00        |
| <b>Labour</b>                                                                                                                                           |          |          |                   |               |
| 15 REMOVE & REFIX FRT BUMPER & ATTACHMENTS, HEADLAMP, FRT LH FENDER, FRT LH DOOR & ATTACHMENTS; KNOCKING & REPAIR FRT LH DOOR PILLAR & REALIGN THE SAME | 600.00   | 1 LA     | 600.00            | <i>450</i>    |
| 16 PUTTY & RESPRAY FRT BUMPER, FRT LH FENDER, FRT LH DOOR & PILLAR & ALL AFFECTED AREAS                                                                 | 700.00   | 1 LA     | 700.00            | <i>600</i>    |
| 17 REMOVE & REFIX FRT WHEEL, KNUCKLE ARM, BEARING & REALIGN THE SAME                                                                                    | 180.00   | 1 LA     | 180.00            | X             |
| 18 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT                                                                                                              | 60.00    | 1 PC     | 60.00             | ✓             |
| 19 REMOVE & REFIX FRT LH DOOR WINDOW GLASS & RESET CENTRAL LOCKING                                                                                      | 50.00    | 1 LA     | 50.00             | ✓             |
| 20 RUSTPROOFING                                                                                                                                         | 60.00    | 1 LA     | 60.00             | ✓             |
|                                                                                                                                                         |          |          | 1,650.00          | 1,650.00      |
| Total                                                                                                                                                   |          |          | S\$ 6,449.04      |               |
| Add GST @ 7%                                                                                                                                            |          |          | 451.43            |               |
| Total Amount Payable                                                                                                                                    |          |          | S\$ 6,900.47      |               |

\*SURVEY VEHICLE AT ANG MO KIO WORKSHOP

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

For Cheng Hoe Motor Pte Ltd

*[Signature]*  
 AUTHORISED SIGNATURE