



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|---|--|------------|
| AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG | | | Ref: CC4/ASM22000980/Vga3q2 Date: 02/08/2022 Code: ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SHA 6999D | Veh. Inspected | GY 5953C |
| | Policy No. | P2465679 | Coverage (\$) | 0.00 |
| | Claim No. | S2M03RZ7 | Excess (\$) | 0.00 |
| | Assign From | | Assign Date | 27/01/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | TOYOTA HIACE | c.c | 2982 |
| | Engine No. | HIDDEN | Year of Reg. | 2005 |
| | Chassis No. | JTFHS02P200013587 | Colour | WHITE |
| | Odometer | 325983 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 195 R15C | GT RADIAL | 5 mm |
| | L/H Front Tyre | 195 R15C | GT RADIAL | 5 mm |
| | R/H Rear Tyre | 195 R15C | GT RADIAL | 5 mm |
| | L/H Rear Tyre | 195 R15C | GT RADIAL | 5 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 20/01/2022 | Inspection Date | 09/02/2022 |
| | Survey held at | TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934. | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | |