



**TeamWork Garage Pte Ltd**  
 53 Ubi Avenue 1 #01-23/24 Spore 408934  
 Paya Ubi Industrial Park  
 Tel : 6844 2475  
 E-mail : claims@teamworkgarage.com  
 ROC number : 201015366H  
**REPAIR PERFORMA INVOICE**

AXA

|                |                   |
|----------------|-------------------|
| Vehicle number | GY5953C           |
| Make / Model   | TOYOTA HIACE AUTO |
| Chassis number | JTFHS02P200013587 |
| Accident date  | 20/1/22           |
| Reference      | 2201-22           |

| Qty                                           | Particulars                                | Unit Price - SGD \$ |
|-----------------------------------------------|--------------------------------------------|---------------------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u>         |                                            |                     |
| 1                                             | FRONT BUMPER                               | 595.32 / Cut        |
| 1                                             | FRONT BUMPER RETAINER LH                   | 79.00 / nec         |
| 1                                             | FRONT BUMPER COVER LH                      | 104.00 XNN          |
| 1                                             | FRONT STEP GARNISH LH                      | 69.84 / Scr         |
| 1                                             | FRONT STEP PANEL LH                        | 178.09 / Scr        |
| 1                                             | FRONT HEADLAMP LH                          | 818.40 / Scr 589    |
| 1                                             | FRONT HEADLAMP BRACKET LH                  | 128.30 / Cut        |
| 1                                             | FRONT DOOR PANEL LH                        | 1778.90 Xr          |
| 2                                             | FRONT DOOR HINGE                           | 68.00 XSVU          |
|                                               |                                            | 3819.85             |
|                                               | Less 25%                                   | 954.97              |
|                                               |                                            | 2864.88             |
| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> |                                            |                     |
| 1 SET                                         | FRONT BUMPER CLIP                          | 30.00 20            |
| 1                                             | DOOR COMPANY DECAL                         | 80.00 30            |
|                                               | Subtotal                                   | 110.00              |
|                                               | Balance C/F                                | 2974.88             |
| <u>LABOUR AND MISCELLANEOUS CHARGES</u>       |                                            |                     |
| 1                                             | CHECK WIRING AND LIGHTNING SYSTEM          | 60.00 20            |
| 2                                             | REMOVE AND REFIT DOOR MECHANISM FOR REPAIR | 200.00 XNN          |
| 3                                             | PANEL BEATING ON AFFECTED AREAS            | 800.00 500          |
| 4                                             | SPRAY PAINTING ON AFFECTED AREAS           | 800.00 300          |
| 5                                             | APPLY ANTI RUST ON AFFECTED AREAS          | 150.00 30           |
|                                               | Subtotal                                   | 2010.00             |
|                                               | Grand total                                | 4984.88             |

Tham 82239769  
 9/2/22 1300  
 US 3days wp

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: