

AXA

Vehicle number	GY5953C
Make / Model	TOYOTA HIACE AUTO
Chassis number	JTFHS02P200013587
Accident date	20/1/22
Reference	2201-22

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER	595.32 / Cut
1	FRONT BUMPER RETAINER LH	79.00 / Rec
1	FRONT BUMPER COVER LH	104.00 Xmn
1	FRONT STEP GARNISH LH	69.84 / Scr
1	FRONT STEP PANEL LH	178.09 / Scr
1	FRONT HEADLAMP LH	818.40 / Scr
1	FRONT HEADLAMP BRACKET LH	128.30 / Cut
1	FRONT DOOR PANEL LH	1778.90 Xr
2	FRONT DOOR HINGE	68.00 X Scr
		3819.85
	Less 25%	954.97
		2864.88
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT BUMPER CLIP	30.00 20
1	DOOR COMPANY DECAL	80.00 30
	Subtotal	110.00
	Balance C/F	2974.88
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 20
2	REMOVE AND REFIT DOOR MECHANISM FOR REPAIR	200.00 XNN
3	PANEL BEATING ON AFFECTED AREAS	800.00 500
4	SPRAY PAINTING ON AFFECTED AREAS	800.00 300
5	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
	Subtotal	2010.00
	Grand total	4984.88

Thuan 82235769
9/2/22 1300
US 3days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: