



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2302435

INV Date 18/04/2023

Reference CC4/LPC22000982/Rpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJQ 7245G
Insured Veh. GBD 8065R
Claim No. 21/22/22/VC05/025401
Policy No. Z21VC05007420
Accident Date 22/01/2022
Inspection Date 27/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22000982/Rpa3q2 Date: 18/04/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 8065R	Veh. Inspected	SJQ 7245G
	Policy No.	Z21VC05007420	Coverage (\$)	0.00
	Claim No.	21/22/22/VC05/025401	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	27/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI LANCER 1.6 CVT SP	c.c	1584
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JMYSTCS3A9U005479	Colour	BLUE
	Odometer	222480 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/50 R15	TOURADOR	6 mm
	L/H Front Tyre	195/50 R15	TOURADOR	6 mm
	R/H Rear Tyre	195/50 R15	TOURADOR	6 mm
	L/H Rear Tyre	195/50 R15	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/01/2022	Inspection Date	27/01/2022
	Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 7245G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	710.00	688.00
2	FRONT BUMPER UPPER GRILLE @\$86.00	SCRATCHED	172.00	172.00
1	FRONT BUMPER UPPER GRILLE BASE	NOT NECESSARY	280.00	-
1	FRONT BUMPER UPPER GRILLE LOGO	NECESSARY	38.00	38.00
1	FRONT BUMPER NUMBER PLATE HOLDER	SCRATCHED	147.00	82.00
2	FRONT BUMPER BEAM @\$79.00	NOT NECESSARY	158.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	298.00	166.00
1	BONNET	TO REPAIR SEE LABOUR	629.00	-
1	FRONT BRACE PANEL LOCK	NOT NECESSARY	146.00	-
2	HEAD LAMP @\$567.00	NOT NECESSARY	1,134.00	-
2	HEAD LAMP LOWER BRACKET @\$45.00	NOT NECESSARY	90.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	590.00	-
1	BOOT LID	BENT	593.00	593.00
1	BOOT LID STOPPER	NECESSARY	26.00	26.00
1	BOOT LID EMBLEM 'LANCER'	NOT NECESSARY	54.00	-
1	BOOT LID EMBLEM 'GLX'	NOT NECESSARY	54.00	-
1	BOOT LID LOGO	NOT NECESSARY	55.00	-
1	BOOT LID TOP LOCK	SCRATCHED	146.00	70.00
1	BOOT LID LOWER LOCK	NOT NECESSARY	38.00	-
1	BOOT LID NUMBER PLATE GARNISH	SCRATCHED	198.00	192.00
1	BOOT LID WEATHER STRIP	CUT	169.00	150.00
1	REAR BUMPER	DEFORMED	789.00	710.00
1	REAR BUMPER CENTER BEAM	NOT NECESSARY	194.00	-
2	REAR BUMPER SIDE RETAINER @\$54.00	NOT NECESSARY	108.00	-
2	TAIL LAMP @\$484.00	NOT NECESSARY	968.00	-
2	TAIL LAMP PANEL @\$196.00	NOT NECESSARY	392.00	-
2	REAR FENDER @\$698.0	N/S TO REPAIR SEE LABOUR / O/S NOT NECESSARY	1,396.00	-
2	REAR FENDER INNER COWLING @\$97.00	NOT NECESSARY	194.00	-

Report Ref No. CC4/LPC22000982/Rpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER TRIM @\$279.00	CRACKED	558.00	424.00
2	REAR FENDER AIR VENT @\$64.00	NOT NECESSARY	128.00	-
2	REAR WINDSCREEN SIDE MOULDING @\$230.00	NOT NECESSARY	460.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	115.00	-
1	REAR DOOR INNER LOCK	NOT NECESSARY	397.00	-
1	REAR END PANEL	BENT	414.00	414.00
1	REAR END PANEL TOP GARNISH	CRACKED	150.00	150.00
1	REAR FLOOR PANEL	NOT NECESSARY	998.00	-
1	REAR FLOOR PANEL TOP BOARD	CRACKED	147.00	147.00
1	REAR SPARE TYRE BOLT	NOT NECESSARY	48.00	-
	LESS 10% DISCOUNT		-1,318.10	-402.20
			11,862.90	3,619.80
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	CRACKED	50.00	35.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	65.00	30.00
1	FRONT BUMPER LOWER LIP (SPECIAL TYPE) (SN)	NOT NECESSARY	1,800.00	-
1	SET FRONT BUMPER UPPER GRILLE CLIPS (SN)	NECESSARY	30.00	20.00
1	SET FRONT FENDER COWLING CLIP (SN)	NOT NECESSARY	60.00	-
1	RADIATOR COOLANT (SN)	NOT NECESSARY	60.00	-
1	REAR NUMBER PLATE (SN)	SCRATCHED	50.00	35.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	REAR BUMPER LOWER LIP (SPECIAL TYPE) (SN)	CRACKED	1,800.00	700.00
1	BOOT LID SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET BOOT LID NUMBER PLATE GARNISH CLIP (SN)	NOT NECESSARY	50.00	-
1	SET TAIL LAMP CLIP (SN)	NOT NECESSARY	30.00	-
2	TAIL LAMP PANEL SEALANT @\$80.00 (SN)	NOT NECESSARY	160.00	-
2	REAR FENDER SEALANT @\$80.00 (SN)	NOT NECESSARY	160.00	-
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	60.00	-
10	REAR FENDER INNER TRIM CLIPS @\$6.50 (SN)	NECESSARY	65.00	30.00
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	60.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
4	REAR END PANEL TOP GARNISH CLIPS @\$6.50 (SN)	NECESSARY	26.00	20.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	120.00	40.00

Report Ref No. CC4/LPC22000982/Rpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	250.00	-
1	TRIANGLE BREAKDOWN SIGN (SN)	NOT NECESSARY	180.00	-
1	REVERSE SENSOR (SN)	NOT WORKING	220.00	220.00
			5,516.00	1,160.00
	LABOUR			
	PANEL BEATING ,REMOVING AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF BONNET AND FRONT SUPPORT PANEL .		1,000.00	400.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	600.00
	WIRING CHECK.		50.00	30.00
	REFOCUS HEADLAMP BEAM.	NOT NECESSARY	80.00	-
	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.	NOT NECESSARY	80.00	-
	TO PANEL BEAT ,WELD ,CUT ,GRAZE ,KNOCK STRAIGHTEN ,ADJUST AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER LH.		1,800.00	800.00
	TO PUTTY ,SPRAY PAINT POLISH ,WAX.		1,800.00	1,000.00
	TO SPRAY TUFF COAT.		250.00	80.00
	WIRING BULB CHECKING.		80.00	30.00
	REMOVE AND REFIX UPHOLSTERY TO FACILITATE REPAIR.		150.00	60.00
	REMOVE AND REFIX REAR EXHAUST PIPE.	NOT NECESSARY	150.00	-
	CONDUCT WATER LEAKAGE TEST .	NOT NECESSARY	80.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	60.00
	REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX FUEL TANK TO FACILITATE REAR FLOOR PANEL REPLACEMENT.	NOT NECESSARY	80.00	-
	REAR CHASSIS ALIGNMENT.	NOT NECESSARY	250.00	-
			7,170.00	3,060.00
GRAND TOTAL			24,548.90	7,839.80

Report Ref No. CC4/LPC22000982/Rpa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,250.00
---	--	--	----------

Report Ref No. CC4/LPC22000982/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJQ 7245G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJQ 7245G

RE-INSPECTION

