



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: GARNET			Ref: CC4/ASM22000983/Bpa3q2 Date: 09/09/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 5949A	Veh. Inspected	SMP 5997C
	Policy No.	P1937443	Coverage (\$)	0.00
	Claim No.	S2M03ROH	Excess (\$)	0.00
	Assign From		Assign Date	27/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE 1.5G	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GK82001141	Colour	BLACK
	Odometer	243868 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	POOR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	MICHELIN	4 mm
	L/H Front Tyre	185/60 R15	MICHELIN	4 mm
	R/H Rear Tyre	185/60 R15	MICHELIN	4 mm
	L/H Rear Tyre	185/60 R15	MICHELIN	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION & O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/01/2022	Inspection Date	04/02/2022
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		25 Working Days	