

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

TP MSG.

Veron.

ESTIMATE

Name : MOHAMAD NOOR BIN MOHD

Make/Model : HONDA CIVIC

Vehicle No : SMM 1910 U

Accident date : 27.01.2022

No	DESCRIPTION	Qty	Amount (\$S)
List Items			
1	Rear bootlid <i>new</i>	1	\$ 554.90 x
2	Rear bootlid "H" emblem <i>3x new</i>	1	\$ 29.20 x
3	Rear bootlid "Civic" emblem	1	\$ 38.20 x
4	Rear bumper <i>behind</i>	1	\$ 677.20 ✓
5	Rear bumper side holder @ \$28.70 <i>new</i>	2	\$ 57.40 ✓
6	Rear bumper lower lip <i>behind</i>	1	\$ 198.70 ✓
7	Rear bumper lower lip protector <i>cut</i>	1	\$ 78.20 ✓
8	Rear bumper towing hook cover <i>new</i>	1	\$ 38.00 x
9	Rear bumper reinforcement <i>dent</i>	1	\$ 280.00 ✓
10	Rear end panel <i>Reis</i>	1	\$ 277.80 x
			\$ 2,229.60
Less 20% Disc			\$ 445.92
Total			\$ 1,783.68
Special Nett Items			
1	Rear bumper reverse sensor (1 set) <i>Damaged</i>	1	\$ 280.00 <i>20</i>
2	Rear bumper clips (1 set) <i>new</i>	1	\$ 60.00 <i>30</i>
Total			\$ 340.00
Labour Cost			
1	To supply rear end panel inner sealant		\$ 50.00 x
2	Remove & refix reverse sensor		\$ 150.00 <i>50</i>
3	Remove & refix bootlid garnish		\$ 200.00 x
4	Remove ,replace & repair consistent to the accident		\$ 1,000.00 <i>300</i>
5	Respray painting		\$ 1,000.00 <i>400</i>
Total			\$ 2,400.00
Grand Total			\$ 4,523.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2013.20

(P/P) 20

03 Days

214