

Kang Car Repairers Pte Ltd

No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
Singapore 417883

Tel: 67477636 Fax: 67485071 Email: kangcar@singnet.com.sg;kangcar176@yahoo.com.sg

INSURER: **India International Insurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	KCR0120222113III/OD
Policy No:	D20MFL0000618-02	Date of Loss:	26/01/2022
Vehicle Reg. No.:	SND2113H	Driveable?	
Driver Age/Info:	22 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO DRIVING CENTRE PTE LTD	Contact No:	+6590072819
Driver:	LEE CHUAN LING, MICHELLE		

Make/Model:	TOYOTA COROLLA, 1.5 AXIO (M)	Vehicle Reg. Date:	14/12/2021
Vehicle Colour:	SILVER		
Engine No:	1NZ9331039	Chassis No:	NZE1617133790
Odometer:	845 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Present Location: KANG CAR REPAIRERS PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	1,762.95
Miscellaneous Items	130.00
Labour	1,550.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	3,442.95
+ GST 7.00% (S\$)	241.01
Nett Amount (S\$)	3,683.96

This claim is handled by: YEE MEI CHENG

*Generated using **Merimen e-Claims Internet Estimation & Adjusting System***

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 Jan 2022)**Parts:** 143 TOYOTA COROLLA 1.5 AXIO (M) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Kang Car Repairers Pte Ltd/SND2113H/27/01/2022 15:23**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER LH	0.00	0.00	*250.00 F
2	1		*FRONT FENDER COWLING LH	0.00	0.00	*105.00 F
3	1		*HEAD LAMP LH	0.00	0.00	*340.00 F
4	1		*FRONT BUMPER	0.00	0.00	*700.00 F
5	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	*58.00 F
6	1		*FRONT BUMPER FOG LAMP COVER LH	0.00	0.00	*80.00 F

F=Franchise part.

Sub Total (\$)	1,533.00
+ Margin on L,N Items 15.00% (\$)	229.95
Total Parts (\$)	1,762.95

Kang Car Repairers Pte Ltd/SND2113H/27/01/2022 15:23. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT BUMPER CLIPS	60.00
2	1	FRONT FENDER COWLING CLIPS	40.00
3	1	FRONT FENDER NUMBER 720 STICKER	30.00
Sub Total (S\$)			130.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	50.00
2	TO SPRAY PAINTING (FRONT)	New	800.00
3	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING/WELDING WORKS	New	700.00
Gross Labour Cost (S\$)			1,550.00

Kang Car Repairers Pte Ltd/SND2113H/27/01/2022 15:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >