

Steve (LKK)
28/1/22, 3:00pm

WAL
LIS
WAL
8 dgs

Quotation

DATE: 26/01/22
VEHICLE NO: PA6559X
DRIVER: MOHD RAZIB BIN BUJANG
ATTENTION TO:
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
Q REF No: Q22/01/1246
DEPARTMENT: WTS Bus Department
ACCIDENT DATE: 25/01/22
REF No: JW-0122-75

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	REAR BUMPER / <i>OK</i>	1	2000	2,000.00
2	REAR RHS DOOR / <i>OK</i>	1	4000	4,000.00
3	REAR LHS DOOR / <i>OK</i>	1	4000	4,000.00
4	REAR RHS DOOR GLASS / <i>OK</i>	1	350	350.00
5	REAR RHS DOOR GLASS RUBBER / <i>OK</i>	1	200	200.00
6	REAR LHS CORNER PANEL / <i>OK</i>	1	4500	4,500.00
7	60 KM STICKER / <i>OK</i>	1	5	5.00
8	REAR NUMER PLATE X	1	30	30.00
9	WOODLANDS TRANSPORT REAR STICKER / <i>OK</i>	1	150	150.00
10	CHILDREN TRIANGLE CROSS SIGN. / <i>OK</i>	1	250	250.00
Labour Costs				
1	TO DISMANTLE AND RE-INSTALL REAR PASSENGER SEATS FOR FACILITATE REPAIR REAR BOTH SIDE DOOR PANEL AND CORNER PANEL. <i>20%</i>	1	500	500.00
2	TO DISMANTLE DAMAGED PARTS TO REPAIR AND REPLACE BOTH SIDE DOOR, REAR BUMPER AND CORNER PANEL.	1	2000	2,000.00
3	TO CHECK WIRING AND INSTALL CHILDREN CROSS SIGN.	1	180	180.00
4	TO REMOVE DAMAGED PARTS AND INSTALL REAR RHS DOOR GLASS WITH RUBBER	1	250	250.00
Spray Paint				
1	Spray Painting TO SPRAY PAINTING REAR BUMPER, REAR BOTH SIDE DOOR PANEL AND REAR LHS CORNER PANEL.	1	2200	2,200.00
TOTAL:				20,615.00
Total Amount				SGD 20,615.00

Remarks:

LKK Auto Consultants henceforth
the Repairer of the Vehicle
Signature of Workshop Dpt
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Thomas 26/01/2022
Signature of Department Head

Signature of Claim Department