

ASS. REC. BY: Steve

REF: CS/CT172000988/ERY3

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: PC 203B  
 Policy No. DMB1SNW00014432000  
 Claims No. SNM22D200686/C02/THAMYL  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
| X   | X   |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: PA6559X Yr Regn: 26/9/06  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or 3908  
 Make: MITSUBISHI BE639 c.c. 4847  
 Colour MINT-Colour A/C: Insured / Std / NI / NA  
 Sp. Reading 931777 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: BE639JD 00379  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modl: NII / S/Rim / STD A/Rim or  
 Tyre Size: F: 215/75R17.5  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

|                                                                   |                       |
|-------------------------------------------------------------------|-----------------------|
| Front                                                             | Rear                  |
| R/Bal. <u>4</u> mm                                                | R/Bal. <u>4</u> mm    |
| L/Bal. <u>4</u> mm                                                | L/Bal. <u>4</u> mm    |
| D.O.A. <u>25/1/22</u>                                             | D.O.I. <u>28/1/22</u> |
| Survey held at <u>Woodlands Transport</u>                         |                       |
| Des. of Damages: Frt / <u>Rear</u> / O/S / N/S / U/C / Rooftop or |                       |

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                       |
|-------------|--------------------------------------------|
|             | <u>MV-45K</u>                              |
| 14/2/22     | Steve informed LS \$8550 (Red 12,065, 58%) |
|             |                                            |
|             |                                            |
|             |                                            |
|             |                                            |
|             |                                            |

Date/Time, File Pass to?

☐ : Prel. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2) 23/2/22-typist

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: Merimen

Lump Sum / t.B.t: (\$ 8550 )

Steve (LKK)  
28/1/22, 3:00pm

WAL  
LIS  
WAL  
8 dys

## Quotation

DATE: 26/01/22  
VEHICLE NO: PA6559X  
DRIVER: MOHD RAZIB BIN BUJANG  
ATTENTION TO:  
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop  
Q REF No: Q22/01/1246  
DEPARTMENT: WTS Bus Department  
ACCIDENT DATE: 25/01/22  
REF No: JW-0122-75

| S/N                 | Description                                                                                                                   | Qty | Cost per Unit | Amount S\$           |
|---------------------|-------------------------------------------------------------------------------------------------------------------------------|-----|---------------|----------------------|
| <b>Spare Parts</b>  |                                                                                                                               |     |               |                      |
| 1                   | REAR BUMPER / <i>OK</i>                                                                                                       | 1   | 2000          | 2,000.00             |
| 2                   | REAR RHS DOOR / <i>OK</i>                                                                                                     | 1   | 4000          | 4,000.00             |
| 3                   | REAR LHS DOOR / <i>OK</i>                                                                                                     | 1   | 4000          | 4,000.00             |
| 4                   | REAR RHS DOOR GLASS / <i>OK</i>                                                                                               | 1   | 350           | 350.00               |
| 5                   | REAR RHS DOOR GLASS RUBBER / <i>OK</i>                                                                                        | 1   | 200           | 200.00               |
| 6                   | REAR LHS CORNER PANEL / <i>OK</i>                                                                                             | 1   | 4500          | 4,500.00             |
| 7                   | 60 KM STICKER / <i>OK</i>                                                                                                     | 1   | 5             | 5.00                 |
| 8                   | REAR NUMER PLATE X                                                                                                            | 1   | 30            | 30.00                |
| 9                   | WOODLANDS TRANSPORT REAR STICKER / <i>OK</i>                                                                                  | 1   | 150           | 150.00               |
| 10                  | CHILDREN TRIANGLE CROSS SIGN. / <i>OK</i>                                                                                     | 1   | 250           | 250.00               |
| <b>Labour Costs</b> |                                                                                                                               |     |               |                      |
| 1                   | TO DISMANTLE AND RE-INSTALL REAR PASSENGER SEATS FOR FACILITATE REPAIR REAR BOTH SIDE DOOR PANEL AND CORNER PANEL. <i>20%</i> | 1   | 500           | 500.00               |
| 2                   | TO DISMANTLE DAMAGED PARTS TO REPAIR AND REPLACE BOTH SIDE DOOR, REAR BUMPER AND CORNER PANEL.                                | 1   | 2000          | 2,000.00             |
| 3                   | TO CHECK WIRING AND INSTALL CHILDREN CROSS SIGN.                                                                              | 1   | 180           | 180.00               |
| 4                   | TO REMOVE DAMAGED PARTS AND INSTALL REAR RHS DOOR GLASS WITH RUBBER                                                           | 1   | 250           | 250.00               |
| <b>Spray Paint</b>  |                                                                                                                               |     |               |                      |
| 1                   | Spray Painting<br>TO SPRAY PAINTING REAR BUMPER, REAR BOTH SIDE DOOR PANEL AND REAR LHS CORNER PANEL.                         | 1   | 2200          | 2,200.00             |
| <b>TOTAL:</b>       |                                                                                                                               |     |               | <b>20,615.00</b>     |
| <b>Total Amount</b> |                                                                                                                               |     |               | <b>SGD 20,615.00</b> |

Remarks:

LKK Auto Consultants  
Signature of Workshop Dpt  
26/01/22  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

Signature of Department Head

Signature of Claim Department