

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE: 26/01/22

VEHICLE NO: PA6559X

DRIVER: MOHD RAZIB BIN BUJANG

ATTENTION TO:

PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop

Q REF No: Q22/01/1246


DEPARTMENT: WTS Bus Department

ACCIDENT DATE: 25/01/22

REF No: JW-0122-75


S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	REAR BUMPER	1	2000	2,000.00
2	REAR RHS DOOR	1	4000	4,000.00
3	REAR LHS DOOR	1	4000	4,000.00
4	REAR RHS DOOR GLASS	1	350	350.00
5	REAR RHS DOOR GLASS RUBBER	1	200	200.00
6	REAR LHS CORNER PANEL	1	4500	4,500.00
7	60 KM STICKER	1	5	5.00
8	REAR NUMER PLATE	1	30	30.00
9	WOODLANDS TRANSPORT REAR STICKER	1	150	150.00
10	CHILDREN TRIANGLE CROSS SIGN.	1	250	250.00
Labour Costs				
1	TO DISMANTLE AND RE-INSTALL REAR PASSENGER SEATS FOR FACILITATE REPAIR REAR BOTH SIDE DOOR PANEL AND CORNER PANEL.	1	500	500.00
2	TO DISMANTLE DAMAGED PARTS TO REPAIR AND REPLACE BOTH SIDE DOOR , REAR BUMPER AND CORNER PANEL .	1	2000	2,000.00
3	TO CHECK WIRING AND INSTALL CHILDREN CROSS SIGN.	1	180	180.00
4	TO REMOVE DAMAGED PARTS AND INSTALL REAR RHS DOOR GLASS WITH RUBBER	1	250	250.00
Spray Paint				
1	Spray Painting TO SPRAY PAINTING REAR BUMPER , REAR BOTH SIDE DOOR PANEL AND REAR LHS CORNER PANEL.	1	2200	2,200.00
			TOTAL:	20,615.00
			Total Amount	SGD 20,615.00

Remarks:



26/1/22

Signature of Workshop Dpt



26/01/2022

Signature of Department Head

Signature of Claim Department