



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22000989/Evf3e2	
			Date: 19/05/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMQ 2893H	Veh. Inspected	SKU 9660U
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000279MFQC	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	28/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	LAND ROVER DISCOVERY	c.c	2993
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	SALLAAAG5GA777650	Colour	BROWN
	Odometer	114350 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/55 R19	MICHELIN	5 mm
	L/H Front Tyre	255/55 R19	MICHELIN	5 mm
	R/H Rear Tyre	255/55 R19	MICHELIN	5 mm
	L/H Rear Tyre	255/55 R19	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/01/2022	Inspection Date	03/02/2022
	Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	