

ASS. REC. BY: StereREF: CS/KC122000989/EVf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
☒	☒

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SK49660U Yr Regn: 25/8/15Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Land Rover Discovery c.c. 2999Colour: Brown A/C: ☒ Insured / Std / NI / NASp. Reading: 114350 T/Radio: ☒ Insured / Std / NI / NA

Eng/No: _____

C/No: SALLAAAG5GA177650Gen. Cond: ☒ Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ Nil / ☒ S/Rim / ☐ STD A/Rim orTyre Size: F: 255/55R19R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIG / DHTSU / PIR / SUMI /
TOYO / YOKO orFront R/Bal. 5 mmL/Bal. 5 mmD.O.A. 24/1/22 WarnesSurvey held at 3/2/2022Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MR-137K

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

Steve (LKK)
3/2/22, 11:00am
Wor RL
3 dy
PIP, R1 BL sy

SERVICE ESTIMATE

94711 - C00001 SL: SERVICE SALES - PC
Ms Yeo Wei Min Elaine
12 Jalan Emas Urai

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 27/01/2022

WIP No. . : 11160

Veh.In/Out:

*Tel.No. . : Mobile: 93898500

Reg.No. . : SKU9660U

Reg.date . : 25/08/2015

Mileage . : 0

Chassis No: SALLAAAG5GA777650

Singapore 678734

Closed by : Juan Paulo Bongon Ba
Svc Consultant :

Remarks : Ms Yeo Wei Min Elain

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR BUMPER PAD, REAR BUMPER LOWER, REAR REFLECTOR LH, ETC	0 1300	1500.00	0		1,500.00	S
800	TO SPRAY REAR BUMPER	0 1000	1200.00	0		1,200.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	0		621.00	S
	BUMPER COVER REAR D4 / DD	1.0 EA	2326.60			2,326.60	S
	BUMPER PAD MOULDING / CUT	1.0 EA	215.90			215.90	S
	BUMPER MOULDING TOW / CUT	1.0 EA	130.00			130.00	S
	BUMPER FOAM REAR DIS	1.0 EA	126.10			126.10	S
	BUMPER RELECTOR REAR / BR	1.0 EA	194.90			194.90	S
	BUMPER RELECTOR REAR X	1.0 EA	194.90			194.90	S
	PARKING AID 90 Degre	4.0 EA	367.20			1,468.80	S
	BUMPER BRACKET REAR	1.0 EA	143.50			143.50	S
	BUMPER BRACKET REAR	1.0 EA	143.50			143.50	S
	BUMPER BRACKET REAR	1.0 EA	108.20			108.20	S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

94711 - C00001
 Ms Yeo Wei Min Elaine
 12 Jalan Emas Urai

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2
 Inv.date. : 27/01/2022

WIP No. . : 11160

Veh.In/Out:

*Tel.No. . : Mobile: 93898500

Reg.No. . : SKU9660U

Reg.date . : 25/08/2015

Mileage .. : 0

Chassis No: SALLAAAG5GA777650

Singapore 678734

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : Ms Yeo Wei Min Elain

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET REAR		1.0 EA	108.20			108.20	S
	BUMPER BRACKET REAR		1.0 EA	139.10			139.10	S
	BUMPER BRACKET REAR		1.0 EA	126.40			126.40	S
	GRILLE CLIP EVOQUE		15.0 EA	4.00			60.00	S
	BUMPER BRACKET NUT R		10.0 EA	4.10			41.00	S
	LH CTR SENSOR BRACKE		1.0 EA	18.60			18.60	S
	PDC HOLDER REAR LH D		1.0 EA	20.40			20.40	S

Gross Total. 8,887.10

Labour Total 3,321.00
 Parts Total 5,566.10
 Package Total 0.00

Net..... 8,887.10
 GST @ 7.0% 622.10
 Total..... 9,509.20
 Paid..... 0.00
 Please Pay.. 9,509.20

GST: S=StdRated; O=OutOfScope; Z=ZeroRated