



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897		Ref: CS/AIS22000991/Utf3e2 Date: 18/03/2022 Code: AIS	
<b>1. Policy Particulars :- OWN DAMAGE</b>			
<b>Insured Veh.</b>		<b>Veh. Inspected</b>	SLP 6932U
<b>Policy No.</b>	SP2000258470-01	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	2022 22003799SL	<b>Excess (\$)</b>	600.00
<b>Assign From</b>	SHANTI	<b>Assign Date</b>	28/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	MITSUBISHI OUTLANDER (A)	<b>c.c</b>	2360
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	JMYXTGF3WHZ002287	<b>Colour</b>	BLUE
<b>Odometer</b>	64434 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/55 R18	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	225/55 R18	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	225/55 R18	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	225/55 R18	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION AND REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
<b>Accident Date</b>	19/01/2022	<b>Inspection Date</b>	28/01/2022
<b>Survey held at</b>	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650		
<b>5a. Remarks</b>			
A)THE MARKET VALUE IS S\$69,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>10 Working Days</b>	